Packet Guide City of Charlottesville Board of Architectural Review Regular Meeting November 15, 2022, 5:30 p.m. Hybrid Meeting (In-person at CitySpace and virtual via Zoom)



**Pre-Meeting Discussion** 

**Regular Meeting** 

#### A. Matters from the public not on the agenda [or on the Consent Agenda]

- B. Consent Agenda
  - Certificate of Appropriateness BAR # 22-11-01

     Preston Place, TMP 050118001 and 050118002
     Rugby Road-University Circle-Venable ADC District
     Owner: Sue and Steve Lewis
     Applicant: Leigh Boyes, Sage Designs
     Project: Landscaping
  - 2. <u>Certificate of Appropriateness</u>

BAR # 22-11-02 480 Rugby Road, TMP 090003000 Rugby Road-University Circle-Venable ADC District Owner: Westminster Presbyterian Church Applicant: Breck Gastinger, Local Design Collective Project: Landscaping, site work (Common Grounds)

3. <u>Certificate of Appropriateness</u>

BAR # 22-11-04 402 Park Street, Tax Parcel 530115000 North Downtown ADC District Owner: Anchor Charlottesville Office 2, LLC Applicant: Kendra Moon / Line+Grade Project: Demo drive-through/ATM kiosk. New landscaping.

#### C. Deferred Items

4. <u>Certificate of Appropriateness</u> BAR # 22-09-04 0 3<sup>rd</sup> Street NE, TMP 330020001 North Downtown ADC District Owner: Scott Loughery Applicant: Candace Smith, Architect Project: New residence on vacant lot

#### D. New Items

5. <u>Certificate of Appropriateness</u> BAR # 22-11-03 507 Ridge Street, Tax Parcel 290141000 Ridge Street ADC District Owner/Applicant: Kimberly and Clayton Lauter Project: Demo backyard shed/cottage

6. Certificate of Appropriateness

BAR # 22-11-05 914 Rugby Road. TMP 50145000 Rugby Road Historic Conservation District Owner: Erin and George Sloane Applicant: John Voight / JKV Architects Project: Alterations to front porch, side addition

#### 7. <u>Certificate of Appropriateness</u>

Preliminary Discussion (No action to be taken) 300 Court Square, TMP 530096100 North Downtown ADC District Owner: Eagle Tavern, LLC Applicant: Candace DeLoach, Claudine Wispelwey Project: Exterior alterations

#### 8. <u>Certificate of Appropriateness</u>

Preliminary Discussion (No action to be taken) 204 Hartmans Mill Road, TMP 260038000 Individually Protected Property Owner: Jocelyn Johnson and William Hunt Applicant: Dan Zimmerman / Alloy Workshop Project: Addition and exterior alterations

#### DI. Other Business

9. Mall Trees. Discussion with Parks and Rec

#### 10. Staff questions/discussion

- BAR awards 2022
- Holiday dinner (and alumni reunion)

#### DII. Adjourn

#### **Certificate of Appropriateness**

BAR # 22-11-01 0 Preston Place, TMP 050118001 and 050118002 Rugby Road-University Circle-Venable ADC District Owner: Sue and Steve Lewis Applicant: Leigh Boyes, Sage Designs Project: Landscaping

Application components (please click each link to go directly to PDF page):

- Staff Report
- Application Submittal

City of Charlottesville Board of Architectural Review Staff Report November 15, 2022



# **Certificate of Appropriateness**

BAR # 22-11-01 0 Preston Place, TMP 050118001 (also 508-516 Preston Place) Rugby Road-University Circle-Venable ADC District Owner: Sue and Steve Lewis Applicant: Leigh Boyes, Sage Designs Project: Landscaping



#### **Background**

Year Built:	Extant remnants of c1920-1937 parking garages
District:	Rugby Road-University Circle-Venable Neighborhood ADC
Status:	non-contributing

Parcel historically contained a stone and frames garage complex. All that remains are low segments masonry walls along the west and north borders, which will be retained.

#### **Prior BAR Review**

August 14, 2017 – BAR approved CoA to move Wyndhurst (605 Preston Place) to this lot. Not realized.

February 15, 2022 – BAR preliminary discussion re: single-family residence at 0 Preston Place.

July 19, 2022 - BAR approved CoA for single-family residence.

#### **Application**

• Submittal: Sage Designs drawings Lewis Residence, Preliminary Landscape/Site Plan, dated 11/7/2022: Sheet S1.1.

Request CoA for landscaping plan.

#### **Discussion and Recommendations**

Staff recommends approval with the fencing conditions suggested in the motion. (Note: The initial plan included *mock orange* on the plant list. The applicant has removed that species, due to it being invasive.)

# **Suggested Motions**

*Approval*: Having considered the standards set forth within the City Code, including City Design Guidelines, I move to find that the proposed landscaping at 0 Preston Place satisfies the BAR's criteria and is compatible with this property and other properties in the Rugby Road-University Circle-Venable Neighborhood ADC district, and that the BAR approves the application as submitted with the following conditions:

• New picket fencing in front yard to be similar to those at nearby properties on Preston Place and not exceed a height of 4-ft. New fencing at the side and rear yards to be similar to those at nearby properties on Preston Place and not exceed a height of 6-ft. Where a new rear and/or side yard fence is incorporated into a stone wall, the total height shall not exceed 6-ft. Wood fencing will be either painted or have an opaque stain. Prior to construction the applicant will present the design to staff to assure compliance with this condition and the design guidelines for *Walls and Fences*. [See *Appendix*.]

# Criteria, Standards and Guidelines

# **Review Criteria Generally**

Sec. 34-284(b) of the City Code states that, in considering a particular application the BAR shall approve the application unless it finds:

- (1) That the proposal does not meet specific standards set forth within this division or applicable provisions of the Design Guidelines established by the board pursuant to Sec.34-288(6); and
- (2) The proposal is incompatible with the historic, cultural or architectural character of the district in which the property is located or the protected property that is the subject of the application.

# Pertinent Standards for Review of Construction and Alterations include:

- (1) Whether the material, texture, color, height, scale, mass and placement of the proposed addition, modification or construction are visually and architecturally compatible with the site and the applicable design control district;
- (2) The harmony of the proposed change in terms of overall proportion and the size and placement of entrances, windows, awnings, exterior stairs and signs;
- (3) The Secretary of the Interior Standards for Rehabilitation set forth within the Code of Federal Regulations (36 C.F.R. §67.7(b)), as may be relevant;
- (4) The effect of the proposed change on the historic district neighborhood;
- (5) The impact of the proposed change on other protected features on the property, such as gardens, landscaping, fences, walls and walks;
- (6) Whether the proposed method of construction, renovation or restoration could have an adverse impact on the structure or site, or adjacent buildings or structures;
- (7) Any applicable provisions of the City's Design Guidelines.


# Pertinent ADC District Design Guidelines

# Chapter II - Site Design and Elements

- B. Plantings
- 1. Encourage the maintenance and planting of large trees on private property along the streetfronts, which contribute to an "avenue" effect.
- 2. Generally, use trees and plants that are compatible with the existing plantings in the neighborhood.
- 3. Use trees and plants that are indigenous to the area.
- 4. Retain existing trees and plants that help define the character of the district, especially street trees and hedges.
- 5. Replace diseased or dead plants with like or similar species if appropriate.

- 6. When constructing new buildings, identify and take care to protect significant existing trees and other plantings.
- 7. Choose ground cover plantings that are compatible with adjacent sites, existing site conditions, and the character of the building.
- 8. Select mulching and edging materials carefully and do not use plastic edgings, lava, crushed rock, unnaturally colored mulch or other historically unsuitable materials.
- C. Walls and Fences
- 1) Maintain existing materials such as stone walls, hedges, wooden picket fences, and wrought-iron fences.
- 2) When a portion of a fence needs replacing, salvage original parts for a prominent location.
- 3) Match old fencing in material, height, and detail.
- 4) If it is not possible to match old fencing, use a simplified design of similar materials and height.
- 5) For new fences, use materials that relate to materials in the neighborhood.
- 6) Take design cues from nearby historic fences and walls.
- 7) Chain-link fencing, split rail fences, and vinyl plastic fences should not be used.
- 8) Traditional concrete block walls may be appropriate.
- 9) Modular block wall systems or modular concrete block retaining walls are strongly discouraged but may be appropriate in areas not visible from the public right-of-way.
- 10) If street-front fences or walls are necessary or desirable, they should not exceed four (4) feet in height from the sidewalk or public right-of-way and should use traditional materials and design.
- 11) Residential privacy fences may be appropriate in side or rear yards where not visible from the primary street.
- 12) Fences should not exceed six (6) feet in height in the side and rear yards.
- 13) Fence structures should face the inside of the fenced property.
- 14) Relate commercial privacy fences to the materials of the building. If the commercial property adjoins a residential neighborhood, use a brick or painted wood fence or heavily planted screen as a buffer.
- 15) Avoid the installation of new fences or walls if possible in areas where there are no are no fences or walls and yards are open.
- 16) Retaining walls should respect the scale, materials and context of the site and adjacent properties.
- 17) Respect the existing conditions of the majority of the lots on the street in planning new construction or a rehabilitation of an existing site.
- E. Walkways and Driveways
- 1. Use appropriate traditional paving materials like brick, stone, and scored concrete.
- 2. Concrete pavers are appropriate in new construction, and may be appropriate in site renovations, depending on the context of adjacent building materials, and continuity with the surrounding site and district.
- 3. Gravel or stone dust may be appropriate, but must be contained.
- 4. Stamped concrete and stamped asphalt are not appropriate paving materials.
- 5. Limit asphalt use to driveways and parking areas.
- 6. Place driveways through the front yard only when no rear access to parking is available.
- 7. Do not demolish historic structures to provide areas for parking.
- 8. Add separate pedestrian pathways within larger parking lots, and provide crosswalks at vehicular lanes within a site.


# **Appendix**



Picket Fence







ADC District or IPP

Board of Architectural Review (BAR) Certificate of Appropriateness ADC Districts and IPPs Please Return To: City of Charlottesville Department of Neighborhood Development Services P.O. Box 911. City Hall Staff contacts: Charlottesville, Virginia 22902 Jeff Werner wernerjb@charlottesville.gov Telephone (434) 970-3130
---

Please submit the signed application form and a digital copy of submittal and attachments (via email or thumb drive). Please include application fee as follows: New construction project \$375: Demolition of a contributing structure \$375: Appeal of BAR decision \$125; Additions and other projects requiring BAR approval \$125; Administrative approval \$100. Make checks payable to the City of Charlottesville.

The BAR meets the third Tuesday of the month.

Deadline for submittals is Tuesday 3 weeks prior to next BAR meeting by 3:30 p m.

						1	man and the		
Owner Name	STEVE	-	SVE LEG	115 Appl	licant Name	LEIMH	DONE		0
Project Name/Des	cription	$\bigcirc$	<u>Proto</u> n	BINE_	Pe	arcel Number	0501	18001	18002
Project Property A	ddress	0	RESTON	PLACE,	CT-776 FO	nes ville	E, VA:		

#### Applicant Information

Address:	3033 ALBOLENE CHRIST LN.
cise?	Lecador (2) gmail. com
E hall Phone, (W	434 2.94 7381 434-825-4500

Property Owner Information (if not applicant)

Address: 428 MONROE 22903 CHARLE ITEILINE, LA. Email: <u>ceds</u> Lewis @ amail.com 40.270.1473 C) Phone: (W)

Do you intend to apply for Federal or State Tax Credits for this project? \_\_\_\_\_no

#### Signature of Applicant

I hereby attest that the information I have provided is, to the best of my knowledge orrect.

10.21.2022 Signatur

10.21.2022 YE LE16 Date Print Name

Property Owner Permission (if not applicant) I have read this application and hereby give my consent to

its submission. 10 Signat 10/21/22 Date ewis

Landscaping plan Description of Proposed Work (attach separate narrative if necessary):

List All Attachments (see reverse side for submittal requirements):

For Office Use Only	Approved/Disapproved by: Date:
Received by: Fee paid:Cash/Ck. #	
Date Received:	
Revised 2016	

#### **Certificate of Appropriateness**

BAR # 22-11-02 480 Rugby Road, TMP 090003000 Rugby Road-University Circle-Venable ADC District Owner: Westminster Presbyterian Church Applicant: Breck Gastinger, Local Design Collective Project: Landscaping, site work (Common Grounds)

#### Application components (please click each link to go directly to PDF page):

- Staff Report
- Historic Survey
- Application Submittal

City of Charlottesville Board of Architectural Review Staff Report November 15, 2022

#### **Certificate of Appropriateness**

RUOTTESI HO-VIE HGINIA-IN

408 Rugby Road, TMP 090003000 (Also 1710 Gordon Avenue. Formerly 214 Rugby Road.) Rugby Road-University Circle-Venable ADC District Owner: Westminster Presbyterian Church Applicant: Breck Gastinger, Local Design Collective Project: Landscaping



#### Background

Year Built:c. 1900-1915District:Rugby Road-University Circle-Venable ADC DistrictStatus:Contributing

Built as detached dwelling; now a community coffee-house. Eclectic/Vernacular. Circa 1900-1915. Brick (6-course American bond with Flemish variant on front); 2-1/2-stories; hipped roof; one front oversized hipped dormer; asymmetrical 3-bay front; 3-sided, 2-story projecting front bay; 1- story side porch, now screened. Segmental arches over openings; rounded hood over front door. Characterized by highly articulated facades, this early brick house has served as a nonprofit community coffeehouse since the 1960s.

#### **Prior BAR Reviews**

n/a

# **Application**

• Applicant's submittal: Local Design Collective drawings *Common Grounds Terrace: Westminster Presbyterian Church*, dated October 21, 2022: Sheets 1 through 12.

Request CoA for landscaping and related sitework. (No new exterior lighting is proposed.)

#### **Discussion**

Staff recommends approval as submitted.

Comments from the applicant in response to initial questions.

- Explanation why the large tree visible on Google street view is no longer there.
  - <u>Local Design Collective</u>: The large tree was a mulberry. They can be problematic and there were concerns this tree's roots may be undermining the existing structure. Early in design conversations, removal was suggested as part of this request; however, the owner decided to remove without notifying the design team. That said, Westminster Presbyterian has planted significant canopy trees on other portions of its campus and along Rugby Road: elms, gingko, Kentucky coffee tree, among others. The overhead lines present a challenge to new, canopy-scaled trees at the side yard.
- The dwarf fothergilla and ninebark provide [visual] interest over many seasons; however, fothergilla loses its leaves in winter. Bordering a structure, would an evergreen be preferrable? Explain removal of the boxwood—as neighborhood-defining plant, per the Design Guidelines--and planting fothergilla?
  - Local Design Collective: The boxwood in the front yard will remain. The boxwood in the side yard have grown too large and visually isolate the screened porch from the rest of the yard. The congregation wants the yard and the porch to be more welcoming and conducive to gatherings and activities. The boxwood will not be discarded, but transplanted to the north of the new terrace, screening the adjacent parking. The porch is only a few feet above the yard, therefore the new, lower--and native--plantings are preferred.

#### Suggested motion

*Approval*: Having considered the standards set forth within the City Code, including City's ADC District Design Guidelines, I move to find that the proposed landscaping plan at 480 Rugby Road satisfies the BAR's criteria and are compatible with this property and other properties in the Rugby Road-University Circle-Venable ADC District, and that the BAR approves the application as submitted.

#### Criteria, Standards, and Guidelines

#### **Review Criteria Generally**

Sec. 34-284(b) of the City Code states that, In considering a particular application the BAR shall approve the application unless it finds:

- 1) That the proposal does not meet specific standards set forth within this division or applicable provisions of the Design Guidelines established by the board pursuant to Sec.34-288(6); and
- 2) The proposal is incompatible with the historic, cultural or architectural character of the district in which the property is located or the protected property that is the subject of the application.

#### Pertinent Standards for Review of Construction and Alterations include:

- 1) Whether the material, texture, color, height, scale, mass and placement of the proposed addition, modification or construction are visually and architecturally compatible with the site and the applicable design control district;
- 2) The harmony of the proposed change in terms of overall proportion and the size and placement of entrances, windows, awnings, exterior stairs and signs;
- 3) The Secretary of the Interior Standards for Rehabilitation set forth within the Code of Federal Regulations (36 C.F.R. §67.7(b)), as may be relevant;

- 4) The effect of the proposed change on the historic district neighborhood;
- 5) The impact of the proposed change on other protected features on the property, such as gardens, landscaping, fences, walls and walks;
- 6) Whether the proposed method of construction, renovation or restoration could have an adverse impact on the structure or site, or adjacent buildings or structures;
- 7) Any applicable provisions of the City's Design Guidelines.

#### **Pertinent ADC District Design Guidelines**

Chapter II – Site Design and Elements


B. Plantings

- 1. Encourage the maintenance and planting of large trees on private property along the streetfronts, which contribute to an "avenue" effect.
- 2. Generally, use trees and plants that are compatible with the existing plantings in the neighborhood.
- 3. Use trees and plants that are indigenous to the area.
- 4. Retain existing trees and plants that help define the character of the district, especially street trees and hedges.
- 5. Replace diseased or dead plants with like or similar species if appropriate.
- 6. When constructing new buildings, identify and take care to protect significant existing trees and other plantings.
- 7. Choose ground cover plantings that are compatible with adjacent sites, existing site conditions, and the character of the building.
- 8. Select mulching and edging materials carefully and do not use plastic edgings, lava, crushed rock, unnaturally colored mulch or other historically unsuitable materials.
- E. Walkways and Driveways
- 1. Use appropriate traditional paving materials like brick, stone, and scored concrete.
- 2. Concrete pavers are appropriate in new construction, and may be appropriate in site renovations, depending on the context of adjacent building materials, and continuity with the surrounding site and district.
- 3. Gravel or stone dust may be appropriate, but must be contained.
- 4. Stamped concrete and stamped asphalt are not appropriate paving materials.
- 5. Limit asphalt use to driveways and parking areas.
- 6. Place driveways through the front yard only when no rear access to parking is available.
- 7. Do not demolish historic structures to provide areas for parking.
- 8. Add separate pedestrian pathways within larger parking lots, and provide crosswalks at vehicular lanes within a site.


H. Utilities and Other Site Appurtenances

- 1. Plan the location of overhead wires, utility poles and meters, electrical panels, antennae, trash containers, and exterior mechanical units where they are least likely to detract from the character of the site.
- 2. Screen utilities and other site elements with fences, walls, or plantings.
- 3. Encourage the installation of utility services underground.

Appendix 1920 Sanborn Map



c1965 Sanborn Map



# **Common Grounds Terrace**

Westminster Presbyterian Church

BAR COA application October 21, 2022

# **Project Narrative:**


The intention is to create a small garden space in the side yard of Common Grounds for the Congregation's youth ministries. The garden is formed by new plantings, benches, and tables to create options for teaching, studying, and hosting youth activities.

The new project also improves accessibility throughout the Westminster campus. A rebuilt stair at the porch entrance improves safety and repairs a rotting sill condition. The existing concrete stair will remain, with a new stair and landing constructed on top.

New plantings will create a better garden experience and improved visibility for Common Grounds.









N 0' 2.5' 5'

#### Notes

- ٠ Forsythia only removed on either side of stair.
- Provide bench backs along portions of bench ٠
- Concrete below benches (included in totals) ٠ provides edge to pavers and lawn.
- Pavers to be concrete, permeable paver system ٠ set on clean, angular gravel per manufacturer recommendation. Slope subsurface away from building and provide 4" perforated draintile for any overflow.
- ٠
- Rebuild existing concrete stair to Common Grounds Porch on top of existing stair. Freestanding wood screen/fence provides storage, hides building utilities. 5/4 x 6 wood slats on treated posts. Full 2" x 8" cap. Boards to be prepainted.
- Provide tree/shrub planting and prepare beds at ٠ front of plantings. Annual/perennials by WPC. Benches:
  - Painted steel bases and back supports ٠
  - Rot-resistant native timber locust or equal ٠
  - Corrosion resistant fasteners ٠















(1) Trident mapleAcer buergerianum1.5" cal

(26) Dwarf ninebark *Physocarpus opulifolius* 'Nanus' 3 gal.

PROGRESS PLANTING PLAN





















Materials: Wood Bench Inspiration BAR COA Application October 21, 2022



# EXISTING MATERIALS



SOLID CONTINUOUS TIMBER.
ROT - RESISTANT, NATIVE TIMBER
SPECIES. BLACK LOCUST OR ALTERNATE.

THREADED STAINLESS STEEL BOLT. FASTEN TIMBERS TOGETHER, SEAL WITH WOOD PLUG


3/8" STEEL BOX SUPPORT, EASE ALL EXPOSED EDGES

STAINLESS STEEL BOLT. EMBED INTO EXISTING CONCRETE OR CONCRETE FOOTER (REFER TO PLAN)

- GROUND CONDITIONS VARY, SEE PLANS

	}	File No. 104-130 Negative no(s).		
eetaddress 214 Rugby Road wn/City Charlottesville toric name	Commo	en name Prism Co	ffee House	
terial   log (siding:    weatherbo    stucco    concrete block    enameled steel	eatherboard, Shingle, on sides Stretcher, Course Ameri Candom ashlar, Coursed ashlar ard, Coshingle, aluminum,	pricktex, C cast iron C terra cotta glass and		w/ Flemish vari )
Number of Stories       1     1       2½       1½       2	Roof Type       shed     mansard       gable     gambrel       pediment     parapet       flat     flat		Roof Mat late vood shingle omposition tanding seam meta	□ tile □ pressed tin □ not visible
Dormers Dormer	C hipped □ 1 C	Number of bays	— Main facade 4 5	□ 7 □ 8 □
Porch         Stories           yes         no         1         3           2         2         2	Bays □ 1 (center) (○ 2 ⊡ 1 (side) [] 3	[] 4	General de Side porch, r	
Iding type detached house detached town house row house double house	apartment building     gas station	government commercial (office) commercial (store) railroad	☐ industrial □ school □ church ᠾc <u>offeehc</u>	Duse
e/period Eclectic ation and description of entrance	ante 1920 Date ca. 1900-	; Architect/builde	r	
	cornice/eave typ This larg wide. Of story dem dormer wi 2-over-2 front doo	escriptive information (p be, window type and tri brick painted i-hexagonal bay ndows. The lar sash and segmer r is covered wi type especiall	n, chimneys, addition s much deeper white, it fea and a roof w ge windows ha tal brick hea th an origina	s, alterations) than it is tures a two- th oversized ve original ds. The l rounded
Рното	has housed readings, r	house served anter in the ear the Prism Coff nusical groups cving as a meet	ly 1960s. Since eehouse, which and other enter	nce then, it h sponsors ertainment as
		Bibb; Sanborn	The local division of	0-93

**ADC District or IPP** 



Description of Proposed Work (attach separate narrative if necessary):

Landscaping and site alterations at Common Grounds Terrace, Westminster Presbyterian

List All Attachments (see reverse side for submittal requirements):

for this project? \_\_\_\_\_no

For Office Use Only	Approved/Disapproved by:
Received by:	Date:
Fee paid:Cash/Ck. #	Conditions of approval:
Date Received:	
Revised 2016	

Print Name

Date

HISTORIC DISTRICT ORDINANCE: You can review the *Historical Preservation and Architectural Design Control Overlay Districts* regulations in the City of Charlottesville Zoning Ordinance starting with Section 34-271 online at **charlottesville.gov** or at Municode.com for the City of Charlottesville.

DESIGN REVIEW GUIDELINES: Please refer to the current *ADC Districts Design Guidelines* online at **charlottesville.gov** 

SUBMITTAL REQUIREMENTS: The following information and exhibits shall be submitted along with each application for Certificate of Appropriateness, per Sec. 34-282 (d) in the City of Charlottesville Zoning Ordinance:

(1) Detailed and clear depictions of any proposed changes in the exterior features of the subject property;

(2) Photographs of the subject property and photographs of the buildings on contiguous properties;

(3) One set of samples to show the nature, texture and color of materials proposed;

(4) The history of an existing building or structure, if requested;

(5) For new construction and projects proposing expansion of the footprint of an existing building: a threedimensional model (in physical or digital form);

(6) In the case of a demolition request where structural integrity is at issue, the applicant shall provide a structural evaluation and cost estimates for rehabilitation, prepared by a professional engineer, unless waived by the BAR.

APPEALS: Following a denial the applicant, the director of neighborhood development services, or any aggrieved person may appeal the decision to the city council, by filing a written notice of appeal within ten (10) working days of the date of the decision. Per Sec. 34-286. - City council appeals, an applicant shall set forth, in writing, the grounds for an appeal, including the procedure(s) or standard(s) alleged to have been violated or misapplied by the BAR, and/or any additional information, factors or opinions he or she deems relevant to the application.

#### CHARLOTTESVILLE ARCHITECTURAL DESIGN CONTROL DISTRICTS DESIGN GUIDELINES

Chapter 1 Introduction (Part 1)

http://weblink.charlottesville.org/public/0/edoc/793062/2\_Introduction%20I\_BAR.pdf

Chapter 1 Introduction (Part 2)

http://weblink.charlottesville.org/public/0/edoc/793063/1\_Introduction%20II\_BAR.pdf

Chapter 2 Site Design and Elements

http://weblink.charlottesville.org/public/0/edoc/793064/3\_Chapter%20II%20Site%20Design%20and%20Elements\_BAR.pdf

Chapter 3 New Construction and Additions

http://weblink.charlottesville.org/public/0/edoc/793065/4\_Chapter%20III%20New%20Construction%20and%20Additions\_BAR.pdf

Chapter 4 Rehabilitation

http://weblink.charlottesville.org/public/0/edoc/793066/5\_Chapter%20IV%20Rehabilitation\_BAR.pdf

Chapter 5 Signs, Awnings, Vending, and Cafes

http://weblink.charlottesville.org/public/0/edoc/793067/6\_Chapter%20V%20Signs%20Awnings%20Vending%20and%20Cafes\_BAR.pdf

Chapter 6 Public Improvements

http://weblink.charlottesville.org/public/0/edoc/793068/7\_Chapter%20VI%20Public%20Improvements\_BAR.pdf

Chapter 7 Moving and Demolition

http://weblink.charlottesville.org/public/0/edoc/793069/8\_Chapter%20VII%20Moving%20and%20Demolition\_BAR.pdf

# **Certificate of Appropriateness**

BAR # 22-11-04 402 Park Street, Tax Parcel 530115000 North Downtown ADC District Owner: Anchor Charlottesville Office 2, LLC Applicant: Kendra Moon / Line+Grade Project: Demo drive-through/ATM kiosk. New landscaping.

# Application components (please click each link to go directly to PDF page):

- Staff Report
- Historic Survey
- Application Submittal

City of Charlottesville Board of Architectural Review Staff Report November 15, 2022

#### **Certificate of Appropriateness Application**

BAR # 22-11-04 402 Park Street, Tax Parcel 530115000 North Downtown ADC District Owner: Anchor Charlottesville Office 2, LLC Applicant: Kendra Moon / Line+Grade Project: Demo drive-through/ATM kiosk. New landscaping.





#### Background

Year Built:1974District:North Downtown ADC DistrictStatus:Contributing (bank and drive-through structure)

Prior to the bank, at this corner, facing Park Street, was a two-story brick dwelling (constructed between 1897 and 1901). By the 1960s, it had converted to office use. (See maps in Appendix.)

#### **Prior BAR Actions:**

March 18, 2003 - BAR approved repairs the brick parapets w/metal coping.

<u>March 15, 2011</u> – BAR approved replacement of brick pavers on walkways and courtyard and modification to handrails to deter skateboarders

#### **Application**

• Applicant submittal: Line+Grade Civil Engineering submittal. Narrative and photographs dated October 25, 2022 and Site Plan dated November 3, 2022 (Sheets C1.0, C2.0, and C2.1).

Request CoA for demolition of the drive-through/ATM kiosk and new site work/landscaping related to the reconfiguration of the parking area.

#### **Discussion and Recommendations**

Staff recommends approval with the following condition (included in the suggested motion below):

• Applicant will provide for the BAR record documentation of the existing building. [In addition to the photos provided, documentation will include dimensioned floor plans and elevations. Similar to documentation provided for 1532 Virginia Ave, January 2019.]

#### **Suggested Motions**

*Approval:* Having considered the standards set forth within the City Code, including the ADC District Design Guidelines, I move to find that the proposed demolition and landscaping at 402 Park Street satisfy the BAR's criteria and guidelines and are compatible with this property and other properties in the North Downtown ADC District, and that the BAR approves the application as submitted with the condition that the Applicant will provide for the BAR record documentation of the existing building. [Note: In addition to the photos provided, documentation will include a dimensioned, sketch floor plan and elevations or photographs with dimensions noted.]

#### Criteria, Standards, and Guidelines

# **Review Criteria Generally**

Sec. 34-284(b) of the City Code states that,

- In considering a particular application the BAR shall approve the application unless it finds:
- (1) That the proposal does not meet specific standards set forth within this division or applicable provisions of the Design Guidelines established by the board pursuant to Sec.34-288(6); and
- (2) The proposal is incompatible with the historic, cultural or architectural character of the district in which the property is located or the protected property that is the subject of the application.

#### **Pertinent Standards for Review of Demolitions:**

Sec. 34-278. - Standards for considering demolitions.

The following factors shall be considered in determining whether or not to permit the moving, removing, encapsulation or demolition, in whole or in part, of a contributing structure or protected property:

(a) The historic, architectural or cultural significance, if any, of the specific structure or property, including, without limitation:

(1) The age of the structure or property;

**Applicant comment**: The drive-through is believed to have been built at the same time as the bank, which according to GIS records, was in 1974.

Staff comment: Bank and drive-through built in 1974 per City's records.

(2) Whether it has been designated a National Historic Landmark, listed on the National Register of Historic Places or listed on the Virginia Landmarks Register;

Applicant comment: The structure is not designated or listed on any of the above.

**Staff comment**: The bank is noted in the inventory of the NRHP nomination for the *Charlottesville and Albemarle County Courthouse Historic District* (VDHR #104-0072); however, per the VCRIS record for the property (104-0072-0186), the building is <u>not</u> a contributing resource to the district. The drive-through is <u>not</u> mentioned.

From the NRHP listing. (www.dhr.virginia.gov/historic-registers/104-0072/

• 402 Park Street (United Virginia Bank): brick and glass (common bond); 2 stories; modified gable roof; 3 bays. Commercial with Colonial Revival influence. 1970. Pre-fabricated fixed windows; steel frame with brick facade; large 2-story, plate-glass viewing window to rear walkway.

(3) Whether, and to what extent, the building or structure is associated with a historic person, architect or master craftsmen, or with a historic event;

Applicant comment: The structure is not associated with any of the above.

Staff comment: Concur with applicant.

(4) Whether the building or structure or any of its features, represent an infrequent or the first or last remaining example within the city of a particular architectural style or feature;

Applicant comment: The [drive-through] is not of a distinct architectural style.

**Staff comment**: The bank and the drive-through share the same design and materiality. Within the City, there are other buildings of this period with similar, modern interpretations of traditional forms. The bank building will remain.

(5) Whether the building or structure is of such old or distinctive design, texture or material that it could not be reproduced, or could be reproduced only with great difficulty; and

Applicant comment: The building material is brick and could be easily reproduced.

Staff comment: Concur with applicant.

(6) The degree to which distinguishing characteristics, qualities, features, or materials remain.


**Applicant comment**: The drive-through is proposed to be completely removed. Its materials and style resemble the main structure on the property (the former bank)

Staff comment: Concur with applicant. Additionally, the bank building will remain.

(b) Whether, and to what extent, a contributing structure is linked, historically or aesthetically, to other buildings or structures within an existing major design control district, or is one of a group of properties within such a district whose concentration or continuity possesses greater significance than many of its component buildings.

Applicant comment: The drive-through is linked to the former bank (to remain).

**Staff comment**: The building's design is not linked historically or aesthetically to the surrounding structures, except the 1974 bank, which will remain. Of the 18 structures immediately nearby, the median built-date is 1908: four were built prior to 1854; 14 between 1900 and 1925.



(c) The overall condition and structural integrity of the building or structure, as indicated by studies prepared by a qualified professional engineer and provided by the applicant or other information provided to the board.

**Applicant comment**: No formal assessment has been conducted, but there is visual evidence of disrepair in the masonry. Please see the photo below for evidence of cracking near the building edges.

**Staff comment**: Concur with applicant. The structure shows some disrepair, though nothing visually suggests it is at-risk. Demolition is requested to facilitate the reconfiguration n of the parking area.

(d) Whether, and to what extent, the applicant proposes means, methods or plans for moving, removing, or demolishing the structure or property that preserves portions, features or materials that are significant to the property's historic, architectural, or cultural value.

**Applicant comment**: No portions of the drive-through are planned to be preserved. As mentioned, its architectural style resembles the former bank structure on the property, which is to remain.

**Staff comment**: Proposal is to raze the entire structure; no elements, features or materials will be retained. Staff concurs with the applicant that the building and site are not historically, architecturally, or culturally significant.

#### Pertinent design guidelines re: Site Design and Elements

Link: <u>Chapter 2 Site Design and Elements</u> B. Plantings

- 1) Encourage the maintenance and planting of large trees on private property along the streetfronts, which contribute to the "avenue" effect.
- 2) Generally, use trees and plants that are compatible with the existing plantings in the neighborhood.
- 3) Use trees and plants that are indigenous to the area.
- 4) Retain existing trees and plants that help define the character of the district, especially street trees and hedges.
- 5) Replace diseased or dead plants with like or similar species if appropriate.
- 6) When constructing new buildings, identify and take care to protect significant existing trees and other plantings.
- 7) Choose ground cover plantings that are compatible with adjacent sites, existing site conditions, and the character of the building.
- 8) Select mulching and edging materials carefully and do not use plastic edgings, lava, crushed rock, unnaturally colored mulch or other historically unsuitable materials.
- F. Parking Areas and Lots
- 1) If new parking areas are necessary, construct them so that they reinforce the street wall of buildings and the grid system of rectangular blocks in commercial areas.
- 2) Locate parking lots behind buildings.
- 3) Screen parking lots from streets, sidewalks, and neighboring sites through the use of walls, trees, and plantings of a height and type appropriate to reduce the visual impact year-round.
- 4) Avoid creating parking areas in the front yards of historic building sites.
- 5) Avoid excessive curb cuts to gain entry to parking areas.
- 6) Avoid large expanses of asphalt.
- 7) On large lots, provide interior plantings and pedestrian walkways.
- 8) Provide screening from adjacent land uses as needed.
- 9) Install adequate lighting in parking areas to provide security in evening hours.
- 10) Select lighting fixtures that are appropriate to a historic setting.

# Pertinent design guidelines re: Demolitions

Link: Chapter 7 Moving and Demolition

- B. Demolition of Historic Structures
- Review Criteria for Demolition
- 1) The standards established by the City Code, Section 34-278.

Staff comment: See comments under Standards for considering demolitions.

2) The public necessity of the proposed demolition.

**Staff comment**: Demolition is not a public necessity; the building has not been condemned or deemed unsafe.

3) The public purpose or interest in land or buildings to be protected.

Staff comment: See comments under Standards for considering demolitions, item a.

4) Whether or not a relocation of the structure would be a practical and preferable alternative to demolition.

Staff comment: See comments under Standards for considering demolitions, item d.

5) Whether or not the proposed demolition would adversely or positively affect other historic buildings or the character of the historic district.

Staff comment: See comments under Standards for considering demolitions, item d.

6) The reason for demolishing the structure and whether or not alternatives exist.

Staff comment: See comments under Standards for considering demolitions, item d.


7) Whether or not there has been a professional economic and structural feasibility study for rehabilitating or reusing the structure and whether or not its findings support the proposed demolition.

Staff comment: See comments under Standards for considering demolitions, item c


#### Guidelines for Demolition


- 1) Demolish a historic structure only after all preferable alternatives have been exhausted.
- 2) Document the building thoroughly through photographs and, for especially significant buildings, measured drawings according to Historic American Buildings Survey (HABS) Standards. This information should be retained by the City of Charlottesville Department of Neighborhood Development Services and the Virginia Department of Historic Resources.
- 3) If the site is to remain vacant for any length of time, maintain the empty lot in a manner consistent with other open spaces in the districts.


Appendix 1877 Gray map



Sanborn Maps







## LINE+GRADE

#### DEMOLITION APPLICATION

- TO: Board of Architectural Review City of Charlottesville
- FROM: Kendra Moon, PE Line and Grade Civil Engineering
- DATE: October 25, 2022
- RE: 402 Park Street Drive-through Demolition Request

#### **Property Details:**

Parcel ID Numbers:	530115000
Total Acres:	0.62
Owner:	Anchor Charlottesville Office 2, LLC
Property Address:	402 Park Street
Current Tenant:	Anchor Health Properties (Office)
Zoning:	DNH
ADC District:	North Downtown

#### A. Demolition Request

The applicant hereby requests to demolish the drive-through that was built to accompany the former bank located at the corner of Park Street and E. High Street (please see Images 1 and 2). The former bank (Image 3) is now an office building, therefore the drive-through is no longer needed. The applicant would prefer to remove this structure and add a few more parking spaces to the lot. All ADC standards for considering demolitions are met.





113 4<sup>th</sup> St. NE; STE 100 CHARLOTTESVILLE, VA 22902 TEL: (434) 262-0169 LINE-GRADE.COM

Image 1. Structure location

402 Park Street Drive-through Demolition Request October 25, 2022 | Page 2



Image 2. Drive-through structure to be demolished



Image 3. Former bank on subject property, to remain (credit: Google)

#### B. Structure Description

The drive-through is 178 sf, 18.9 ft in height, and of brick construction, with a stretcher bond pattern and soldier course header. The roof is metal and gable-style, built to match that of the former bank building on the property. The structure style may be described as American Modern, built in 1974.



#### 402 Park Street Drive-through Demolition Request October 25, 2022 | Page 3

The structure is exhibiting signs of disrepair in the masonry, especially at the joints above the "window" openings where the steel rods are integrated for structural support. Though the structure could be repaired, it is not of use to the current owner.



Image 4. Visual disrepair in brick joints

Also of note is the structure's location, which is shielded by buildings from the viewshed of major roads and can only be seen from 7th Street NE and the adjacent parking lot.

#### C. Standards for Considering Demolitions

- a. The historic, architectural or cultural significance, if any, of the specific structure or property, including, without limitation:
  - (1) The age of the structure of property;

The drive-through is believed to have been built at the same time as the bank, which according to GIS records, was in 1974.

(2) Whether it has been designated a National Historic Landmark, listed on the National Register of Historic Places or listed on the Virginia Landmarks Register;

The structure is not designated or listed on any of the above.

(3) Whether, and to what extent, the building or structure is associated with a historic person, architect or master craftsmen, or with a historic event;

#### The structure is not associated with any of the above.

(4) Whether the building or structure or any of its features, represent an infrequent or the first or last remaining example within the city of a particular architectural style or feature;

The building structure is not of a distinct architectural style.

(5) Whether the building or structure is of such old or distinctive design, texture or material that it could not be reproduced, or could be reproduced only with great difficulty; and

The building material is brick and could be easily reproduced.



(6) The degree to which distinguishing characteristics, qualities, features, or materials remain.

The drive-through is proposed to be completely removed. Its materials and style resemble the main structure on the property (the former bank).

b. Whether, and to what extent, a contributing structure is linked, historically or aesthetically, to other buildings or structures within an existing major design control district, or is one of a group of properties within such a district whose concentration or continuity possesses greater significance than many of its component buildings.

The drive-through is linked to the former bank (to remain).

c. The overall condition and structural integrity of the building or structure, as indicated by studies prepared by a qualified professional engineer and provided by the applicant or other information provided to the board.

No formal assessment has been conducted, but there is visual evidence of disrepair in the masonry. Please see the photo below for evidence of cracking near the building edges.

d. Whether, and to what extent, the applicant proposes means, methods or plans for moving, removing, or demolishing the structure or property that preserves portions, features or materials that are significant to the property's historic, architectural, or cultural value.

No portions of the drive-through are planned to be preserved. As mentioned, its architectural style resembles the former bank structure on the property, which is to remain.

#### D. Conclusion

Though this drive-through is designated a contributing structure, it is not of historical significance and is not included on any historic registry. It was built for a specific function which is no longer useful to the current property owner and building tenant. Its style and materials are easily reproducible and mimic the main building on site, which is to be preserved.


#### List of Appendices


Appendix A: Site Plan Amendment Sheets C1.0 and C2.0 Appendix B: Additional Building Photographs



#### Appendix A

Site Plan Amendment Sheets C1.0 and C2.0





#### Appendix B

#### Additional Building Photographs



Photo 1. Eastern view



Photo 2. Northeastern view



Photo 3. Northwestern view



Photo 4. Southwestern view

Property Names Name Explanation Function/Location Historic Historic Property Addresses Current - 402 Park Street	<b>Name</b> Bank, 402 Park Street Sun Trust Bank United Virginia Bank	<b>Property Evaluation Status</b> Not Evaluated This Property is associated with the Charlottesville and Albemarle County Courthouse Historic District.
County/Independent City(s):	Charlottesville (Ind. City)	
Incorporated Town(s):	No Data	
Zip Code(s):	22902	
Magisterial District(s):	No Data	
Tax Parcel(s):	No Data	
USGS Quad(s):	CHARLOTTESVILLE EAST	

Additional Property Information		
Architecture Setting:	Urban	
Acreage:	No Data	
Site Description:		
Located on the northeast corner that is northeast of the building	of Park Street and High Street in downtown Charlottesville. The parcel includes a paved parking lot	
Surveyor Assessment:		
United Virginia Bank, construc	ted ca 1970-1975. Noncontributing.	
Surveyor Recommendation:	Recommended for Further Survey	
Ownership		
<b>Ownership Category</b> Private	Ownership Entity No Data	

#### **Primary Resource Information**

Primary Resource Information	
<b>Resource Category:</b>	Commerce/Trade
Resource Type:	Bank
NR Resource Type:	Building
Historic District Status:	Non-contributing
Date of Construction:	Ca 1970
Date Source:	Written Data
Historic Time Period:	The New Dominion (1946 - 1991)
Historic Context(s):	Commerce/Trade
Other ID Number:	No Data
Architectural Style:	Other
Form:	No Data
Number of Stories:	2.0
Condition:	Good
Threats to Resource:	None Known
Cultural Affiliations:	No Data
<b>Cultural Affiliation Details:</b>	
No Data	
Architectural Description:	
HD inventory: 402 Park (Uni	ted Virginia Bank): brick and glass (common bond); 2 stories; modified gable roof; 3 bays. Commercial with

#### Virginia Department of Historic Resources Architectural Survey Form

Colonial Revival influence. 1970. Pre-fabricated fixed windows; steel frame with brick façade; large 2-story, plate-glass viewing window to rear walkway.

#### Exterior Components

**Component** Structural System and Exterior Treatment **Component Type** Masonry

**Material** Brick Material Treatment American/Common Bond

#### **Secondary Resource Information**

# Historic District InformationHistoric District Name:Charlottesville and Albemarle County Courthouse Historic DistrictLocal Historic District Name:No DataHistoric District Significance:Charlottesville has been a regional political center since becoming the Albemarle County seat in 1762. In<br/>addition to its associations with Thomas Jefferson and the University of Virginia, the city is significant for<br/>the diversity of its 19th- and early-20th-century architecture. The heart of the district is the courthouse<br/>square, containing the courthouse and several 19th-century brick offices. Also in the district is an<br/>archetypical late-19th-century main street which was made into a pedestrian mall in the 1970s. Architectural<br/>highlights are the former public library, the former post office, and a railroad station, all employing a<br/>learned classicism. Adjacent industrial buildings and several adjoining residential neighborhoods complete<br/>the district. Scattered through the district are various Federal and Greek Revival houses. While not devoid<br/>of intrusions, the district gives Charlottesville's downtown a strong sense of historical continuity.

#### **CRM Events**

#### Event Type: Survey: Phase I/Reconnaissance

<b>Project Review File Number:</b>	No Data	
Investigator:	UVA Student Survey	
Organization/Company:	UVA	
Photographic Media:	Film	
Survey Date:	4/15/1980	
Dhr Library Report Number:	No Data	
Project Staff/Notes:		
No Data		

#### **Bibliographic Information**

Bibliography:

No Data

**Property Notes:** 

No Data

**ADC District or IPP** 



#### Board of Architectural Review (BAR) Certificate of Appropriateness ADC Districts and IPPs Please Return To: City of Charlottesville Department of Neighborhood Development Services P.O. Box 911, City Hall Staff contacts: Charlottesville, Virginia 22902 Jeff Werner wernerjb@charlottesville.gov Telephone (434) 970-3130

Please submit the signed application form and a digital copy of submittal and attachments (via email or thumb drive). Please include application fee as follows: New construction project \$375; Demolition of a contributing structure \$375; Appeal of BAR decision \$125; Additions and other projects requiring BAR approval \$125; Administrative approval \$100. Make checks payable to the City of Charlottesville. The BAR meets the third Tuesday of the month. Deadling for exemptiate is Tuesday 2 works prior to payt PAR meeting by 2:20 p.m. for Admin Review

Deadline for submittals is Tuesday 3 weeks prior to next BAR meeting by 3:30 p.m.

Owner Name Anchor Ch	arlottesville Office 2, LLC	_ Applicant Name_Kendra Moon	
Project Name/Description_	402 Park Street	Parcel Number_	530115000 + 530122100
Project Property Address_	402 Park Street		

#### Applicant Information

Address: 113 4th St NE, STE 100
Charlottesville, VA 22902
Email: kmoon@line-grade.com
Phone: (W) <u>434-262-0169</u> (C) <u>540-660-5744</u>

#### Property Owner Information (if not applicant)

Address: 425 7th St NE	
Charlottesville, VA 22902	
Email: jnelson@anchorhealthproperties.com	
Phone: (W) <u>434-989-7138</u> (C)	

Do you intend to apply for Federal or State Tax Credits for this project? \_\_\_\_\_\_

#### Signature of Applicant

I hereby attest that the information I have provided is, to the best of my knowledge, correct.

Kendraz Moon	10/19/2022
Signature	Date

Kendra G. Moon	10/19/2022
Print Name	Date

Property Owner Permission (if not applicant) I have read this application and hereby give my consent to its submission.

for the d Nelsen	10/19/22
Signature	Date
Jonathan L. Nelson	10/19/22
Print Name	Date

Description of Proposed Work (attach separate narrative if necessary): Change of use for existing financial institution to office space. Demolition of drive-through structure (contributing) and minor improvements to parking area. Reference Line and Grade SPA for 402 Park Street.

List All Attachments (see reverse side for submittal requirements): Narrative including proposed changes, existing building photos, and consistency with ADC standards

For Office Use Only	Approved/Disapproved by:
Received by:	Date:
Fee paid: 1250 Cash/Ck. # 0500	Conditions of approval:
Date Received: 0287072	
Revised 2016	
	e - J.L. L

#### Certificate of Appropriateness BAR # 22-09-04 0 3<sup>rd</sup> Street NE, TMP 330020001 North Downtown ADC District Owner: Scott Loughery Applicant: Candace Smith, Architect Project: New residence on vacant lot


Application components (please click each link to go directly to PDF page):

- Staff Report
- Application Submittal

City of Charlottesville Board of Architectural Review Staff Report November 15, 2022

**Certificate of Appropriateness** BAR 22-09-01 0 3<sup>rd</sup> Street NE, TMP 330020001 North Downtown ADC District Owner: Scott Loughery Applicant: Candace Smith/Architect Project: New residence





#### **Background**

Year Built:n/a. (According to available information, parcel has never been developed.)District:North Downtown ADC DistrictStatus:n/a

#### **Prior BAR Review**

<u>September 20, 2022</u> – BAR held preliminary discussion re: new residence. Link to meeting video. Discussion begins at 02:30:00. <u>https://boxcast.tv/channel/vabajtzezuyv3iclkx1a?b=nvdouryu5aooh1orqwxd</u> Link to Sept 20, 2022 submittal, go to pdf page 100 of: <u>Sept 20 2022 BAR Packet</u>

<u>October 18, 2022</u> - BAR reviewed new residence; accepted applicant's request for a deferral. Link to the BAR meeting video. Discussion begins at 0:03:30. <u>https://boxcast.tv/channel/vabajtzezuyv3iclkx1a?b=uzjazbhfohchjty5hs6f</u> Link to October 18, 2022 submittal, go to pdf page 27 of: <u>October 2022 BAR packet</u>

#### **Application**

• Submittal: Candace M.P. Smith, Architects PC narrative and drawings, dated for November 15, 2022 BAR meeting (11 pages).

CoA request to construct a new single-family residence and detached garage on vacant parcel.

**Note**: Applicant is <u>not</u> seeking final BAR action during this meeting. Rather, the discussion is intended to resolve any outstanding questions prior to the final submittal.

#### **Discussion**

Applicant seeks BAR input on the following:

- Variation of building height.
- Porch options presented, including roof forms and railings.
- o Front gate.
- Color palette.

#### **Suggested Motions**

No action is recommended, except to accept the applicant's request for a deferral.

#### **Criteria, Standards and Guidelines**

#### **Review Criteria Generally**

Sec. 34-284(b) of the City Code states that, in considering a particular application the BAR shall approve the application unless it finds:

- (1) That the proposal does not meet specific standards set forth within this division or applicable provisions of the Design Guidelines established by the board pursuant to Sec.34-288(6); and
- (2) The proposal is incompatible with the historic, cultural or architectural character of the district in which the property is located or the protected property that is the subject of the application.

#### Pertinent Standards for Review of Construction and Alterations include:

- (1) Whether the material, texture, color, height, scale, mass and placement of the proposed addition, modification or construction are visually and architecturally compatible with the site and the applicable design control district;
- (2) The harmony of the proposed change in terms of overall proportion and the size and placement of entrances, windows, awnings, exterior stairs and signs;
- (3) The Secretary of the Interior Standards for Rehabilitation set forth within the Code of Federal Regulations (36 C.F.R. §67.7(b)), as may be relevant;
- (4) The effect of the proposed change on the historic district neighborhood;
- (5) The impact of the proposed change on other protected features on the property, such as gardens, landscaping, fences, walls and walks;
- (6) Whether the proposed method of construction, renovation or restoration could have an adverse impact on the structure or site, or adjacent buildings or structures;
- (7) Any applicable provisions of the City's Design Guidelines.

#### Links to the Design Guidelines:

<u>Chapter 1 Introduction (Part 1)</u> <u>Chapter 1 Introduction (Part 2)</u> <u>Chapter 2 Site Design and Elements</u> Chapter 3 New Construction and Additions

#### Pertinent Guidelines for New Construction and Additions include:

D. Massing and Footprint

[...]

- 2) New infill construction in residential sub-areas should relate in footprint and massing to the majority of surrounding historic dwellings.
- 3) Neighborhood transitional buildings should have small building footprints similar to nearby dwellings.

- a. If the footprint is larger, their massing should be reduced to relate to the smallerscaled forms of residential structures.
- b. Techniques to reduce massing could include stepping back upper levels, adding residential roof and porch forms, and using sympathetic materials.

[...]

E. Height and Width

- 1) Respect the directional expression of the majority of surrounding buildings. In commercial areas, respect the expression of any adjacent historic buildings, which generally will have a more vertical expression.
- Attempt to keep the height and width of new buildings within a maximum of 200 percent of the prevailing height and width in the surrounding sub-area.
   [...]
- 5) Reinforce the human scale of the historic districts by including elements such as porches, entrances, storefronts, and decorative features depending on the character of the particular subarea.

#### F. Scale

1) Provide features on new construction that reinforce the scale and character of the surrounding area, whether human or monumental. Include elements such as storefronts, vertical and horizontal divisions, upper story windows, and decorative features.

#### G. Roof

- 1) Roof Forms and Pitches
  - a. The roof design of new downtown or West Main Street commercial infill buildings generally should be flat or sloped behind a parapet wall.
  - b. Neighborhood transitional buildings should use roof forms that relate to the neighboring residential forms instead of the flat or sloping commercial form.
  - c. Institutional buildings that are freestanding may have a gable or hipped roof with variations.
  - d. Large-scale, multi-lot buildings should have a varied roof line to break up the mass of the design using gable and/or hipped forms.
  - e. Shallow pitched roofs and flat roofs may be\_appropriate in historic residential areas on a contemporary designed building.
  - f. Do not use mansard-type roofs on commercial buildings; they were not used historically in Charlottesville's downtown area, nor are they appropriate on West Main Street.
- 2) Roof Materials: Common roof materials in the historic districts include metal, slate, and composition shingles.
  - a. For new construction in the historic districts, use traditional roofing materials such as standing-seam metal or slate.
  - b. In some cases, shingles that mimic the appearance of slate may be acceptable.
  - c. Pre-painted standing-seam metal roof material is permitted, but commercial-looking ridge caps or ridge vents are not appropriate on residential structures.
  - d. Avoid using thick wood cedar shakes if using wood shingles; instead, use more historically appropriate wood shingles that are thinner and have a smoother finish.
  - e. If using composition asphalt shingles, do not use light colors. Consider using neutralcolored or darker, plain or textured-type shingles.

- f. The width of the pan and the seam height on a standing-seam metal roof should be consistent with the size of pan and seam height usually found on a building of a similar period.
- J. Porches
- 1) Porches and other semi-public spaces are important in establishing layers or zones of intermediate spaces within the streetscape.
- L. Foundation and Cornice
- 1) Distinguish the foundation from the rest of the structure through the use of different materials, patterns, or textures.
- 2) Respect the height, contrast of materials, and textures of foundations on surrounding historic buildings.
- 3) If used, cornices should be in proportion to the rest of the building.
- 4) Wood or metal cornices are preferred. The use of fypon may be appropriate where the location is not immediately adjacent to pedestrians.
- M. Materials and Textures
- 1) The selection of materials and textures for a new building should be compatible with and complementary to neighboring buildings.
- 2) In order to strengthen the traditional image of the residential areas of the historic districts, brick, stucco, and wood siding are the most appropriate materials for new buildings.
- 3) In commercial/office areas, brick is generally the most appropriate material for new structures. "Thin set" brick is not permitted. Stone is more commonly used for site walls than buildings.
- 4) Large-scale, multi-lot buildings, whose primary facades have been divided into different bays and planes to relate to existing neighboring buildings, can have varied materials, shades, and textures.
- 5) Synthetic siding and trim, including, vinyl and aluminum, are not historic cladding materials in the historic districts, and their use should be avoided.
- 6) Cementitious siding, such as HardiPlank boards and panels, are appropriate.
- 7) Concrete or metal panels may be appropriate.
- 8) Metal storefronts in clear or bronze are appropriate.
- 9) The use of Exterior Insulation and Finish Systems (EIFS) is discouraged but may be approved on items such as gables where it cannot be seen or damaged. It requires careful design of the location of control joints.
- 10) The use of fiberglass-reinforced plastic is discouraged. If used, it must be painted.
- 11) All exterior trim woodwork, decking and flooring must be painted, or may be stained solid if not visible from public right-of-way.

N. Paint

- 1) The selection and use of colors for a new building should be coordinated and compatible with adjacent buildings, not intrusive.
- 2) In Charlottesville's historic districts, various traditional shaded of brick red, white, yellow, tan, green, or gray are appropriate. For more information on colors traditionally used on historic structures and the placement of color on a building, see Chapter 4: Rehabilitation.
- 3) Do not paint unpainted masonry surfaces.
- 4) It is proper to paint individual details different colors.

- 5) More lively color schemes may be appropriate in certain sub-areas dependent on the context of the sub-areas and the design of the building.
- O. Details and Decoration
- 1) Building detail and ornamentation should be consistent with and related to the architecture of the surrounding context and district.
- 2) The mass of larger buildings may be reduced using articulated design details.
- 3) Pedestrian scale may be reinforced with details.

#### CANDACE M. P. SMITH ARCHITECT, P.C.

202 SIXTH STREET NE CHARLOTTESVILLE, VA 22902 TEL.: 434.963.4500 FAX: 434.979.1936 WWW.CMPSARCHITECT.COM

#### NARRATIVE AND LIST OF ATTACHMENTS for Board of Architectural Review Meeting November 15, 2022 Preliminary Discussion

Re: New Residence near Hedge Street and Park Plaza (3<sup>rd</sup> St. NE, Parcel #330020001) in Charlottesville, VA—"0 Third Street NE"

#### <u>Narrative</u>

See prior narrative for description of site limitations and materials submitted for 9/20/22 BAR meeting for first preliminary discussion. And prior minutes for plans and earlier 3D sketchup of proposed new house.

Responding to the board's comments, we have reduced the height of the house, determined that siding over a brick foundation is most suitable for reducing the scale of the overall height of the home, and prepared several questions for the Board to discuss so we can move to final approval at the December BAR meeting.

Primary questions focus on the front porch form, and three are presented, with the client's preference noted. Different roof forms and railings are shown. We would appreciate the Board providing their recommendation on this.

Solid gates, similar to others in the neighborhood, will be painted, wood gates with solid panels, similar to the chosen garage doors. (Specifications on the garage doors will be provided at final but have been made.) Railings at the side, screened porches will be solid privacy panels. Paint colors have been selected and paint chips will be available to view at the11/15/22 meeting and will be specified at final submittal.

Finally, a diagram of the street view of the uphill neighbor, our proposed house front at 3<sup>rd</sup> Street NE, and the downhill neighbor at Park Plaza is included to show the slope of the road, comparative finish floor heights and approximate roof peaks/ridges.

Updated landscape plans and other requirements will be met and submitted for the December BAR.

BAR Narrative & Attached Items For Preliminary Discussion Meeting November 15, 2022 Page 2

#### **List of Attachments**

- 1. SK4 (7) sheets showing
  - a. Shorter front and side elevation
  - b. Three front porches
  - c. Front gate detail
- 2. SK4 Addendum
  - a. Street profile diagram



CANDACE M.P. SMITH ARCHITECT, PC 202 SIXTH ST. NE PO BOX 2431 CHARLOTTESVILLE, VA 22902 T:434.963.4500 F:434.979.1936 DISCUSSION DETAILS BAR 11/15/22 FOR SCOTT LOUGHREY NEAR HEDGE ST. & PARK PLAZA SHORTER HOUSE, SIDING & BRICK DATE: 11/15/22 DRAWING SCALE: 1/8" = 1'-0" PROJECT NO: 2204 REVISION DATE: © CANDACE M.P. SMITH ARCHITECT, PC 2022 SK4 1 OF 7






CANDACE M.P. SMITH ARCHITECT, PC 202 SIXTH ST. NE PO BOX 2431 CHARLOTTESVILLE, VA 22902 T:434.963.4500 F:434.979.1936 DISCUSSION DETAILS BAR 11/15/22 FOR SCOTT LOUGHREY NEAR HEDGE ST. & PARK PLAZA FRONT PORCH OPTIONS DATE: 11/15/22 DRAWING SCALE: 1/8" = 1'-0" PROJECT NO: 2204 REVISION DATE: © CANDACE M.P. SMITH ARCHITECT, PC 2022 SK4 3 OF 7




CANDACE M.P. SMITH ARCHITECT, PC 202 SIXTH ST. NE PO BOX 2431 CHARLOTTESVILLE, VA 22902 T:434.963.4500 F:434.979.1936 DISCUSSION DETAILS BAR 11/15/22 FOR SCOTT LOUGHREY NEAR HEDGE ST. & PARK PLAZA FRONT PORCH OPTIONS DATE: 11/15/22 DRAWING SCALE: 1/8" = 1'-0" PROJECT NO: 2204 REVISION DATE: © CANDACE M.P. SMITH ARCHITECT, PC 2022 SK4 4 OF 7





CANDACE M.P. SMITH ARCHITECT, PC 202 SIXTH ST. NE PO BOX 2431 CHARLOTTESVILLE, VA 22902 T:434.963.4500 F:434.979.1936 DISCUSSION DETAILS BAR 11/15/22 FOR SCOTT LOUGHREY NEAR HEDGE ST. & PARK PLAZA FRONT PORCH OPTIONS DATE: 11/15/22 DRAWING SCALE: 1/8" = 1'-0" PROJECT NO: 2204 REVISION DATE: © CANDACE M.P. SMITH ARCHITECT, PC 2022 SK4 5 OF 7





CANDACE M.P. SMITH architect, pc
202 SIXTH ST. NE PO BOX 2431 Charlottesville, va 22902 T:434.963.4500 F:434.979.1936
DISCUSSION DETAILS BAR 11/15/22 FOR
SCOTT LOUGHREY
NEAR HEDGE ST. & PARK PLAZA
APPROXIMATE
PAINT COLORS
DATE: 11/15/22 DRAWING SCALE: 3/8" = 1'-0" PROJECT NO: 2204 REVISION DATE: © CANDACE M.P. SMITH ARCHITECT, PC 2022
SK4 7 OF 7





CANDACE M.P. SMITH ARCHITECT, PC

202 SIXTH ST. NE PO BOX 2431 CHARLOTTESVILLE, VA 22902 T:434.963.4500 F:434.979.1936

DISCUSSION DETAILS BAR 11/15/22 FOR

### SCOTT LOUGHREY

NEAR HEDGE ST. & PARK PLAZA

#### SITE PLAN-NEW GATE LOCATION

DATE: DRAWING SCALE: PROJECT NO: REVISION DATE:

11/15/22 1/8" = 1'-0" 2204

© CANDACE M.P. SMITH ARCHITECT, PC 2022





Board of Architectural Review (BAR)Certificate of Appropriateness ADC Districts and IPPsPlease Return To: City of CharlottesvilleDepartment of Neighborhood Development ServicesP.O. Box 911, City HallCharlottesville, Virginia 22902Telephone (434) 970-3130Robert Watkins watkinsro@charlottesville.gov

Please submit ten (10) hard copies and one (1) digital copy of application form and all attachments. Please include application fee as follows: New construction project \$375; Demolition of a contributing structure \$375; Appeal of BAR decision \$125; Additions and other projects requiring BAR approval \$125; Administrative approval \$100. Make checks payable to the City of Charlottesville. The BAR meets the third Tuesday of the month.

The bark meets the third Tuesday of the month.

Deadline for submittals is Tuesday 3 weeks prior to next BAR meeting by 3:30 p.m.

Owner Name_Scott Loughrey	Applicant Name Candace Smith, Architect,	
Project Name/Description New Residence	Parcel Number_ 330020001	
Project Property Address_0 3rd Street, NE		
Applicant Information	Signature of Applicant	

Address: Candace M.P. Smith Architect, PC 202 6th Streat NE, Charlottesville, Va 22902 Email: candys@cmpsarchitect.com

(C)

#### Property Owner Information (if not applicant)

Phone: (W) 434-963-4500

Address: P.O. Box 4784	
Marietta, Ga 30061-4784	······································
Email: scottloughrey@gmail.com	
Phone: (W)	(C) (404) 909-6077

the part of

Do you intend to apply for Federal or State Tax Credits for this project?

I hereby attest that the information I have provided is, to the best of my knowledge, correct.

m Signature

Candace Smith Print Name 8/29/22 Date

Property Owner Permiss	ion (If not applicant)
I have used this application at ats submission	nd hereby give my consent to
O. Vag	LaRougen 12
Signature	Date
Scott Loughrey	8/29/22
Print Name	Date

Description of Proposed Work (attach separate narrative if necessary): Construction of new residence on vacant parcel

List All Attachments (see reverse side for submittal requirements): See attached

For Office Use Only	Approved/Disapproved by:
Received by:	Date:
Fee paid:Cash/Ck. #	Conditions of approval:
Date Received:	«1.114.» 1.114.»
Revised 2016	



#### Certificate of Appropriateness BAR # 22-11-03 507 Ridge Street, Tax Parcel 290141000 Ridge Street ADC District Owner/Applicant: Kimberly and Clayton Lauter Project: Demo backyard shed/cottage

Application components (please click each link to go directly to PDF page):

- Staff Report
- Historic Survey
- Application Submittal

City of Charlottesville Board of Architectural Review Staff Report November 15, 2022

#### **Certificate of Appropriateness Application**

507 Ridge Street, Tax Parcel 290141000 Ridge Street ADC District Owners/Applicants: Clayton & Kimberly Lauter Project: Demolition of shed/cottage





#### **Background**

Year Built:	Cottage/shed (House constructed c1895)
District:	Ridge Street ADC District
Status:	Contributing

The Gianniny-Bailey House contributes to the series of Victorian residences along Ridge Street that date to the 1890s. This two-story, two-bay house was originally weatherboard, now covered with stucco. Notable features include a semi-octagonal projecting bay on the front façade, and Eastlake trim on the second story porch. The structure in the rear was built as a servant's cottage.

#### **Prior BAR Actions**

March 2005: Approve painting of unpainted stucco.

February 2006: Approve partial demolition and addition.

May 2017: Approve roof and built-in gutter replacement.

August 20, 2019: Approve frame-mounted, ground level, solar photovoltaic system in rear yard.

#### **Application**

• Submittal: Photographs of structure with additional notes and photos by staff.

Request CoA for demolition of an approximately 10-ft x 12-ft, single-story, wood-framed structure in the rear yard.

#### **Discussion**

Staff visited the site on November 3, 2022 and found the cottage to be in poor condition, but not at immediate risk of collapse. (See attached photos and summary.) Owners plans to construct an accessory dwelling unit near/at the location of the cottage; however, they also expressed that

regardless of the ADU project, they do not wish to incur further expenses necessary to stabilize and maintain the cottage. With that, the owners have expressed willingness to allow relocation of the structure to another site, should someone express interest in acquiring it and provided the BAR approves the move.

As summarized below, the design guidelines recommend against approving this request. Staff recommends the BAR discuss this matter and defer a decision until the December 20, 2022 BAR meeting—or, to a later date, if the applicant requests deferral. This would provide an opportunity to find a solution that preserves this structure, avoids a potentially contentious appeal to Council (should a demo CoA be denied), and/or avoids actions that might result in leveraging civil fines.

<u>Note</u>: Staff refers to the following provisions of the City Code only as a matter of full disclosure and for information only, not to suggest a possible a path or outcome, nor to provide an enforceable interpretation of the Code.

**Per Sec. 34-277** (*Certificates of appropriateness; demolitions and removals*), the BAR must approve the razing or moving of a contributing structure, except *upon the determination of the building code official that the building or structure is in such a dangerous, hazardous or unsafe condition that it could reasonably be expected to cause death or serious injury*. Having no such determination by the City, that exception does not apply. Additionally, failure to obtain the necessary approval for demolitions, the owner is subject to a civil penalty *not to exceed twice the fair market value of the building or structure, as determined by the city real estate tax assessment at the time of the demolition, razing or moving*. (Sec. 34-86(b). See *Appendix* of this staff report.) The City's current assessment for this structure is \$2,700. (Reference J. Davis email of Nov. 9, 2202.) As such, the fine could not exceed \$5,400.

**Per Sec. 34-281** (*Maintenance and repair required*), the owner of a contributing structure shall not shall allow it to *fall into a state of disrepair which may result in the deterioration of any exterior appurtenance or architectural feature so as to produce or tend to produce a detrimental effect upon the character of a major architectural design district or the life and character of a contributing structure or protected property*. In a violation of this requirement, the owner is subject to a civil penalty of \$200 for the first violation, and a civil penalty of \$500 for each subsequent violation. (Sec. 34-86(a)(10), see Appendix of this staff report.)

**Per Sec. 34-285** (*Approval or denial of applications by BAR*) and should the BAR deny the CoA, the applicant may appeal to Council and seek further remedy per **Sec. 34-286** (*City council appeals*). (See Appendix of this staff report.)

Should the BAR approve the demolition request, staff recommends the following condition (included in the suggested motion below):

• Applicant will provide for the BAR record documentation of the existing building. [In addition to the photos provided, documentation will include dimensioned floor plans and elevations.]

## **Suggested Motions**

*Approval:* Having considered the standards set forth within the City Code, including the ADC District Design Guidelines, I move to find that the proposed demolition at 507 Ridge Street satisfies the BAR's criteria and guidelines for demolitions and that the BAR approves the application [as submitted with the condition that the applicant will provide for the BAR record documentation of the existing building].

or [as submitted with the following modifications/conditions: ...]

*Denial*: Having considered the standards set forth within the City Code, including the ADC District Design Guidelines, I move to find that the proposed demolition at 507 Ridge Street does not satisfy the BAR's criteria and guidelines for demolitions and that <u>for the following reasons</u> the BAR denies the application as submitted:...

### Criteria, Standards, and Guidelines

#### **Review Criteria Generally**

Sec. 34-284(b) of the City Code states that in considering a particular application the BAR shall approve the application unless it finds:

- (1) That the proposal does not meet specific standards set forth within this division or applicable provisions of the Design Guidelines established by the board pursuant to Sec.34-288(6); and
- (2) The proposal is incompatible with the historic, cultural or architectural character of the district in which the property is located or the protected property that is the subject of the application.

### **Pertinent Standards for Review of Demolitions:**

Sec. 34-278. - Standards for considering demolitions.

The following factors shall be considered in determining whether or not to permit the moving, removing, encapsulation or demolition, in whole or in part, of a contributing structure or protected property:

(a) The historic, architectural or cultural significance, if any, of the specific structure or property, including, without limitation:

(1) The age of the structure or property;

**Staff comment**: The house and cottage were constructed in 1895 by Edgar Gianniny, the proprietor of the Gleason Hotel on West Main. (Passing through several owners, the property was acquired in 1940 by Grover Bailey, whose family occupied the house until 1962.) The available Sanborn Maps suggest the cottage was relocated at least once on the property.

(2) Whether it has been designated a National Historic Landmark, listed on the National Register of Historic Places or listed on the Virginia Landmarks Register;

**Staff comment**: The house and cottage (VDR #104-0025-0019) are listed as contributing structures to the NRHP-listed *Ridge Street Historic District* (VDHR #104-0025). The VCRIS record indicates the property was found ineligible for individual listing. The cottage is identified as *one of the three surviving servants quarters in the Ridge Street Historic District*. [Note: Staff is researching the location

or condition of other, similar structures. That information will be presented at the November 15, 2022 meeting.]

From the NRHP listing. <u>https://www.dhr.virginia.gov/historic-registers/104-0025/</u>507 [Ridge]: (Gianniny-Bailey House); frame (stucco covered weatherboard); 2 story; 2 bays; high pitched hip roof with pedimented gables over 3 projecting bays; one story veranda on north bay. Victorian Vernacular. 1895.

(3) Whether, and to what extent, the building or structure is associated with a historic person, architect or master craftsmen, or with a historic event;

**Staff comment**: Nothing evident in the available records. The builder is not known. The initial owner was Edgar Gianniny, the proprietor of a local hotel.

Servant's cottage: The City's 1994 survey identifies this structure as a servant's *cottage*. According to the US Census and City Directories (between 1900 and 1960) and the City survey, we know the property changed ownership six times and until 1950 was primarily occupied by multiple renters. From the census record, two of the earliest owners had a servant listed in their household; however, neither lived at 507 Ridge Street for those census years. (See the Appendix.) Staff believes reference to a servant's cottage most likely originated with Edgar Gianniny, who reportedly constructed the house in 1895. We cannot determine if Gianniny ever lived here initially; he sold the property in 1897 and in 1900 the house is occupied by a renter. (Curiously, Gianniny does not appear in the 1900 census and the 1910 census lists no one at 507 Ridge Street.) Gianniny reacquired the property in 1901. The biennial City Directories indicate he occupied the house in 1902 and 1904, so we can assume this was between 1901 and 1905. (In 1906, the house is sold to and occupied by Charles Apple.) Per the 1910 census Gianniny lives at 1116 East Market Street, and in the household is Ellen Johnson, age 60, listed as a servant. Also in 1910, Apple has moved to the area near Fry's Spring, and in his household is John Scott, age 15, listed as a servant. It is possible both Gianniny and Apple while living at 507 Ridge Street employed a servant who occupied the cottage. However, the historical record suggests the cottage, if used as a servant's quarters or occupied at all, was likely only from 1895 to 1897 and from 1901 to 1909. [Note: Further research might provide more conclusive evidence.]

(4) Whether the building or structure or any of its features, represent an infrequent or the first or last remaining example within the city of a particular architectural style or feature;

**Staff comment**: The structure is unique in its origin as a *servant's cottage*; however, its style, elements and materiality are very common throughout this district and the City.

(5) Whether the building or structure is of such old or distinctive design, texture or material that it could not be reproduced, or could be reproduced only with great difficulty; and

Staff comment: The building material is easily reproduced.

(6) The degree to which distinguishing characteristics, qualities, features, or materials remain.

**Staff comment**: The structure will be razed (though, the owner may allow its relocation to another site). The applicant has expressed that—unless the building is relocated--salvageable materials will be retained and incorporated (likely as interior elements) in a planned accessory dwelling unit in this location.

(b) Whether, and to what extent, a contributing structure is linked, historically or aesthetically, to other buildings or structures within an existing major design control district, or is one of a group of properties within such a district whose concentration or continuity possesses greater significance than many of its component buildings.

**Staff comment**: The features are less elaborate and ornate than surrounding, similarperiod structures; however, the design and materiality are generally consistent with those buildings.

*Location*: While Sanborn Maps are not reliable for precise scale and dimension, they are generally reliable for spatial relationships. The earliest maps showing this property indicate that between 1902 and 1920, the cottage was located on the south parcel line. On the 1920 map the cottage is either not shown or has moved farther back along the south parcel line. On the 1965 map (and on the 1966 aerial photo) the cottage is at its current location along the north parcel line.

### Pertinent design guidelines re: Demolitions

Link: Chapter 7 Moving and Demolition

A. Introduction

Historic buildings are irreplaceable community assets; and once they are gone, they are gone forever. With each successive demolition or removal, the integrity of a historic district is further eroded. Therefore, the demolition or moving of any contributing building in a historic district should be considered carefully.

Charlottesville's Zoning Ordinance contains provisions that require the property owner to obtain approval prior to demolishing a contributing property in a historic district or an Individually Protected Property (IPP).

The following review criteria should be used for IPP's and (contributing) buildings that are proposed for demolition or relocation.

Plans to demolish or remove a protected property must be approved by the BAR or, on appeal, by the City Council after consultation with the BAR. Upon receipt of an application for demolition or removal of a structure, the BAR has 45 days to either approve or deny the request. If the request is denied and the owner appeals to the City Council, the Council can either approve or deny the request. If Council denies the request, the owner may appeal to the City Circuit Court.

In addition to the right to appeal to City Council or the Circuit Court, there is a process that enables the owner to demolish the building or structure if certain conditions have been met. After the owner has appealed to City Council and has been denied, the owner may choose to make a bona fide offer to sell the building or structure and land. The property must be offered at a price reasonably related to the fair market value of the structure and land and must be made to the city or to any person or firm or agency that gives reasonable assurance that it is willing to preserve and restore the property. City Council must first confirm that the offering price is reasonably related to the fair market value.

The time during which the offer to sell must remain open varies according to the price, as set out in the State Code and the Zoning Ordinance.

If such a bona fide offer to sell is not accepted within the designated time period, the owner may renew the demolition request to City Council and will be entitled [to a CoA that permits demolition].

B. Demolition of Historic Structures
<u>Review Criteria for Demolition</u>
1) The standards established by the City Code, Section 34-278.

Staff comment: See comments under Standards for considering demolitions.

2) The public necessity of the proposed demolition.

**Staff comment**: Demolition is not a public necessity; the building has not been condemned or deemed unsafe.

3) The public purpose or interest in land or buildings to be protected.

Staff comment: See comments under Standards for considering demolitions, item a.

4) Whether or not a relocation of the structure would be a practical and preferable alternative to demolition.

Staff comment: See comments under Standards for considering demolitions, item d.

5) Whether or not the proposed demolition would adversely or positively affect other historic buildings or the character of the historic district.

Staff comment: See comments under Standards for considering demolitions, item d.

6) The reason for demolishing the structure and whether or not alternatives exist.

Staff comment: See comments under Standards for considering demolitions, item d.

7) Whether or not there has been a professional economic and structural feasibility study for rehabilitating or reusing the structure and whether or not its findings support the proposed demolition.

Staff comment: See comments under Standards for considering demolitions, item c

## **Guidelines for Demolition**

- 1) Demolish a historic structure only after all preferable alternatives have been exhausted.
- Document the building thoroughly through photographs and, for especially significant buildings, measured drawings according to Historic American Buildings Survey (HABS) Standards. This information should be retained by the City of Charlottesville Department of Neighborhood Development Services and the Virginia Department of Historic Resources.
- 3) If the site is to remain vacant for any length of time, maintain the empty lot in a manner consistent with other open spaces in the districts.

## Appendix: Related City Code Sections

#### Sec. 34-285. - Approval or denial of applications by BAR.

c) Upon denial of an application (approval of an application with conditions over the objections of the applicant shall be deemed a denial), the applicant shall be provided written notice of the decision, including a statement of the reasons for the denial or for the conditions to which the applicant objects. Following a denial the applicant, the director of neighborhood development services, or any aggrieved person may appeal the decision to the city council, by filing a written notice of appeal within ten (10) working days of the date of the decision.

(9-15-03(3); 12-17-12(1))

### Sec. 34-286. - City council appeals.

- a) An applicant shall set forth, in writing, the grounds for an appeal, including the procedure(s) or standard(s) alleged to have been violated or misapplied by the BAR, and/or any additional information, factors or opinions he or she deems relevant to the application. The applicant, or his agent, and any aggrieved person, shall be given an opportunity to be heard on the appeal.
- b) In any appeal the city council shall consult with the BAR and consider the written appeal, the criteria set forth within section 34-276 or 34-278, as applicable, and any other information, factors, or opinions it deems relevant to the application.
- c) A final decision of the city council may be appealed by the owner of the subject property to the Circuit Court for the City of Charlottesville, by filing with the court a petition at law, setting forth the alleged illegality of the action taken. such petition must be filed with the circuit court within thirty (30) days after council's final decision. The filing of the petition shall stay the council's decision pending the outcome of the appeal; except that the filing of the petition shall not stay a decision of city council denying permission to demolish a building or structure. Any appeal which may be taken to the circuit court from a decision of the city council to deny a permit for the demolition of a building or structure shall not affect the right of the property owner to make the bona fide offer to sell referred to in subparagraphs (d) and (e), below.
- d) In addition to the right of appeal set forth above, the owner of a building or structure, the demolition of which has been the subject of an application appealed to the city council, shall, as a matter of right, be entitled to demolish such building or structure if all of the following conditions have been met:
  - (1) The owner has appealed to city council for permission to demolish the building or structure, and city council has denied such permission;
  - (2) The owner has, for the applicable sale period set forth herein below, and at a price reasonably related to the fair market value of the subject property, made a bona fide offer to sell the building or structure, and the land pertaining thereto, to a person or legal entity that gives reasonable assurance that the building or structure will be preserved and restored; and

- (3) No bona fide contract, binding upon all parties thereto, shall have been executed for the sale of such landmark, building or structure, and the land pertaining thereto, prior to the expiration of the applicable sale period.
- (4) If all of the foregoing conditions are not met within the applicable sale period, then the city council's decision denying a permit shall stand, unless and until that decision is overturned by the circuit court. However, following expiration of the applicable sale period, a property owner may renew his request to the city council to approve the demolition of the historic landmark, building or structure.
- e) The time in which a property owner may take advantage of the rights afforded by subparagraph (d), above (the applicable "sale period") shall be as follows:
  - (1) Three (3) months, when the offering price is less than [\$25,000.00].
  - (2) Four (4) months when the offering price is equal to or greater than [\$25,000] but less than [\$40,000].
  - (3) Five (5) months when the offering price is equal to or is greater than [\$40,000.00] but less than [\$55,000].
  - (4) Six (6) months when the offering price is equal to or greater than [\$55,000] but less than [\$75,000.00].
  - (5) Seven (7) months when the offering price is equal to or is greater than [\$75,000] but less than [\$90,000].
  - (6) Twelve (12) months when the offering price is equal to or greater than [\$90,000].

## Sec. 34-86. - Schedule of civil penalties.

- a) Any violation of the following provisions of this chapter shall be subject to a civil penalty of two hundred dollars (\$200.00) for the first violation, and a civil penalty of five hundred dollars (\$500.00) for each subsequent violation arising from the same set of operative facts:
  - (10) Any violation of Article II, Divisions 1—5, sections <u>34-240</u>, et seq., regarding requirements for overlay districts.
- b) Any person who demolishes, razes or moves any building or structure which is subject to the regulations set forth within section 34-277 or section 34-340 without approval of the BAR or city council, shall be subject to a civil penalty not to exceed twice the fair market value of the building or structure, as determined by the city real estate tax assessment at the time of the demolition, razing or moving.
  - (1) For purposes of this section, the term "person" shall include any individual, firm, partnership, association, corporation, company or organization of any kind, which is deemed by the Charlottesville Circuit Court to be responsible for the demolition, razing or moving.
  - (2) An action seeking the imposition of the penalty shall be instituted by petition filed by the city in the Circuit Court of the City of Charlottesville, which shall be tried in the same manner as any action at law. It shall be the burden of the city to show the liability of the violator by a preponderance of the evidence. An admission of liability or finding of liability shall not be a criminal conviction for any purpose.
  - (3) The defendant may, within twenty-one (21) days after the filing of the petition, file an answer and, without admitting liability, agree to restore the building or structure as it existed prior to demolition. If the restoration is completed within the time agreed upon by the parties or as established by the court, the petition shall be dismissed from the court's docket.

- (4) The filing of the action pursuant to this section shall preclude a criminal prosecution for the same offense, except where the demolition, razing or moving has resulted in personal injury.
- (9-15-03(3); 10-18-10(1); 11-21-11(2); 12-17-12(1))

# 507 Ridge Street - Servant's Cottage c1890s

## NRHP listing: *Ridge Street Historic District*

www.dhr.virginia.gov/wp-content/uploads/2018/04/104-0025\_Ridge\_St\_HD\_1982\_Final\_Nomination-1.pdf 507 Ridge Street: (Gianniny-Bailey House); frame (stucco covered weatherboard); 2 storey; 2 bays; high pitched hip roof with pedimented gables over 3 projecting bays; one storey veranda on north bay. Victorian Vernacular. 1895. (see survey sheet for additional details )



## 507 Ridge Street - Servant's Cottage c1890s

City survey 1994 1-storey, gable roof, white weatherboarded


This house has one of the three surviving servants' quarters in the Ridge Street Historic District. The Gianniny-Bailey House is important to the streetscape and the District.

Oct 2022



Oct 2022





# **GIANNINY-BAILEY HOUSE**



STREET ADDRESS: MAP & PARCEL: VDHR FILE NUMBER: CITY FILE NUMBER: PRESENT ZONING: ORIGINAL OWNER: ORIGINAL USE: PRESENT USE: PRESENT OWNER: ADDRESS:

HISTORIC NAME: DATE/PERIOD: STYLE: HEIGHT(to cornice)OR STORIES: DIMENSIONS AND LAND AREA: CONDITION: SURVEYOR: DATE OF SURVEY: SOURCES:

507 Ridge Street 29-141 104-25-19 364 R-3 E. M. Gianniny Residence Residence Lottie Scott 507 Ridge Street Charlottesville, Virginia Gianniny-Bailey House 1895 Vernacular Queen Anne 2 storeys 60' x 225' (13,500 sq. ft.) Good Bibb Fall 1980, Revised 1993 City Records Mrs. Lottie Scott Mrs. E. A. Talley (Mabel Apple Talley)

# **GIANNINY-BAILEY HOUSE**

#### **ARCHITECTURAL DESCRIPTION**

This house is two storeys tall, two bays wide, and double-pile, set on a low foundation. The original weatherboarding has been covered with stucco, significantly altering the appearance of the house. The trim is painted green. There is a semi-octagonal projecting side bay on the east facade, a rectangular projecting bay on the north side, and a projecting pavilion to the rear. The high-pitched hipped roof has steeply pedimented gables over the three projecting bays and another centered over the southern elevation. The roof is covered with standing-seam metal, painted red, and has Philadelphia gutters, projecting eaves and verges, and a boxed cornice. Brackets with a sunburst motif support the overhanging corners of the gable over the semi-octagonal bay. The sunburst motif is repeated at the peaks of the gables. The rear gable is weatherboarded; the other three are covered with pressed tin. There is a pair of 9-over-9 light tinted glass attic windows in the west facade gable, and a single, plain 1-over-1 light window in each of the others. There are two interior capped chimneys. Other windows are double-sash with architrave trim, 1-over-1 light on the facade and 2-over-2 light elsewhere. The one on the verandah has a panelled spandrel, suggesting that it may originally have been a triple sash window. A deep one-storey verandah covers the northern bay of the facade and wraps around the corner to a side entrance in the projecting bay on the north side. It has a medium-pitched truncated hipped roof covered with standing-seam metal with boxed cornice. The original spool frieze and simple balustrade are gone, square posts have replaced the attenuated Eastlake posts and brackets, and the floor and steps have been replaced with concrete. The wide entrance door in the northern bay has nine lights over three panels and a three-light rectangular transom. Beside the door there is a small double-sash window with one large light bordered by small lights. A small second storey porch is set on the roof of the verandah at window-sill level. It has a nearly flat roof, and it has retained its spool frieze, attenuated Eastlake posts with brackets, and turned balustrade. The second storey hall window gives access to the porch. There is a one-storey hipped-roofed back porch beside the projecting rear pavilion. Interior trim is symmetrically moulded with corner blocks. The three-flight open stair in the entrance hall has a decorated rail and paneled wall. The six fireplaces with Victorian mantels have been closed. There is a one-storey, gable-roofed, white weatherboarded servant's cottage behind the house.

#### HISTORICAL DESCRIPTION

E. M. Gianniny purchased this lot in 1895 (City DB 6-13) and built the house the same year, according to tax records. He sold it to E. M. Buck in 1897 (DB 8-331), then bought it back in 1901 (DB 12-103), and sold it to C. S. Apple in 1906 (DB 17-336). Ida L. Birch bought the house from Apple in 1915 (DB 27-487). Her husband, who had inherited it from her (WB 2-229), lost it during the Depression (DB 69-52, 86-128). E. I. and Mollie F. Bing owned it from 1935 to 1940, when they sold it to G. C. Bailey (DB 102-334). The Bailey family lived there for 22 years before selling it to Mrs. Lottie Scott in 1962 (DB 333-430). The weatherboarding was covered with stucco sometime between 1915 and 1962.

#### STATEMENT OF SIGNIFICANCE

This nicely detailed Vernacular Queen Anne residence is typical of the houses built on Ridge Street in the 1890's. The loss of many of them makes the remaining ones more important. The little second-storey porch, which has retained its Eastlake trim, is especially noteworthy.

This house has one of the three surviving servants' quarters in the Ridge Street Historic District. The Gianniny-Bailey House is important to the streetscape and the District.

GIANNINY- BAILEY HOUSE 507 RIDGE ST. VDHR FILE NO. 104-25-19 1-story porch 996/egible VIA 2<sup>nd</sup>-level parch porch bay topped by pedimented gable Shrubs shrub concrete retaining 2000 sidewalk Ridge St. SUSAN E. SMEAD JANUARY 1994-PRESERVATION ASSOCIATES OF VIRGINIA

29-141 60x225 (13,50 R-3 507 Ridge St. Lottie scott highway plat 8-331 333-430 1972 233-459 1962 102-33? &, C, Bailey 1-fam, 2 storeys, 7 mm, 1/2 baths cone. block found, starco walk, netal gable & hijs reaf, back "old" chege constr frame collage 10'x12 1971 - 'z bath - 'z bath - storage shed 1976 Biam 18,9 10,1 16.2 17.2 16.2 17,2

Danis Mrs & cott stucco before bought ---> come to door - has berman shepherd \* bianning - 1895-1906 = 11 gr Apple - 1906 - 1915 = 9 " Birch - 1915 - 1935 = 20" Bailey - 1946 - 1962 = 22" 5 cott - 1962 - 21981 = 219 yr 5-5581 Bailey

5 × 507 Ridge St 2.33 - 459 Katelika Grover C & Mystle M. Bailey -> Lottie Scott # 12,500 1962 E I & Marg E Bing, & Mollie F. Bing (5) -> & C Bailey same as . 86-128 102-334 5/21/1940 Peo NB, under 1930 dad of trust fr F. H. Birch, widowar, (69-52) -> E. I. Bing & Mollie F. Bing, at auction #3500 lot of impte W side Ridge St 86-128 7/11/1935 same as 27 27-487 69-52 + ind of Ida L. Finch , 1919, WB 2-229 C. S. & Generiève W, Apple -> Eda L. Bruch same ar 17-336 27-487 \$ 4500 10/14/1915 Ella M & E & b'anning -> CS Apple house & lot on west side Ridge & same as 12-103 17-336 # 4000 5/24/1906 EM& Delia C Buck -> EM & ianning, \$3000 let up "honce & other impte" same as 6-13 arlie B. Scribner & hab > Ella M. bianning 8-331 12-103 8/12/1901 Edgar B & Ellam bianning -> EM Back (brack for farm) 8-331 Same an 6-13 house & lat 11/12/1897 Arlie B & W Scubner -> EM bianning (2005. 3) \* lot (no mention of house) on west side Ridge St port of ACD 385-398, 1885, 5 5 M Wolfe est -> Scinbur # 1000 6-13 4/8/1895

Tay 1895 3nd Arlie 3. Scribner w Ridge 1000 + 2000 = 3000 1896 """" " 500 + " = 2500 \* 500 off to Guame " EB Guanning " 700 + 1800 = 2500 fr Scribner"

AD BOOK AD 507 Ridge 2-story, 2-bay Ind, 3 bay 1st low found , cov af cone turco of med green brim high- itched his roof, red 55m, gutter, boyed window Detables over semi-oct proj 5 bay facade = rect proj & bay Vide centered on 5 side, of plandate ; jostor in geble peak; sunbarest como Dalots of plandate ; jostor in geble peak; passet tin ; on 9/2 l tained glass attic windows in font gell, ang reg 1/1 in 5 2 int capped chim windows 1/1, wich trim, 2/2 ades one in prij bay on porch has years ball v deep 1-storeg veranda wrage around NE comer bet ering bage ræther higt lige ref, møtches så pæter pred replace & allake, as i pilæter remaine no balintrale or blug com fly stype ent-worldoor 9l/3 panes 3-l ruch transom side door 12 bordered up small pares sen and storey porch set on porch of I bay of facule nearly flat was spool bring bracketed Eastake post, Vin turned bal stair window on facable 1/1 bordered af small

wants picture 3 fl open stair, der rail, paneled below symmoulded trin uf corner blocks arch beim rear wing gable - mont, w 3 gablen / 1 und en back poch in ell - 15, hip of, eysad rafter ende 1-storey, gable roof, white weatherboarded prob 1 mm

old picture 507 Ridge St e 1906 or 1907 weatherboarded, appears to be light color of white tram low foundation 1/1 windows vocanda : 3 vide styre 557 hig roof, boyed comine Eastlake poste, open (or good?) frieze, simple balistiade Ind storey porch ; same cornice, frieze, poste, but tioned balastrade

# CITY OF CHARLOTTESVILLE "A World Class City"



Department of Neighborhood Development Services

City Hall • P.O. Box 911 Charlottesville, Virginia 22902 Telephone 434-970-3182 Fax 434-970-3359 www.charlottesville.org

April 8, 2003

Mr. Edward W. Wayland c/o 913 East Jefferson Street Charlottesville, VA 22901

## RE: 507 Ridge Street Virginia Historic Landmark Designation

Dear Ed:

We were surprised to learn that the above referenced property is not already on the State's Landmarks list, as it is on the local and national register designations. I am happy to lend our support for designation of this house/property on the Virginia Landmark's list.

This house, known as the Gianniny-Bailey House, dates from 1895, and represents the Victorian style residences built on Ridge Street in the 1890's. The loss of many such residences makes this house an important remaining resource. Such details and features as the Eastlake trim on the second story porch represent items which are rarely seen on homes in Charlottesville. Finally, this house/property has one of the very rare servant's quarters remaining in structures from this era.

I hope this helps to confirm the significance of the structure to the Charlottesville and Virginia Landmarks collection. If you have any questions, please feel free to contact me at 970-3995. Best of luck in obtaining this well-deserved designation.

Sincerely, Ronald L. Higgins, AIC

Planning Manager

RLH:sdp







Date JAN 1994 File	e No. 104-25-19
Name 61ANNINY - BAILEY How	15E , 507 RIDLE ST.
Town <u>CHARLOTTESVILLE</u>	
County	
Photographer ANN C. HUPPE	RT
Contents <u>3 EXT. VIEWS DE</u>	HOUSE, 1 OF
внер	

roperty Names Name Explanation Function/Location Historic/Current Property Addresses Current - 507 Ridge Street	Name Dwelling, 507 Ridge Street Glanny-Bailey House	Property Evaluation Status DHR Evaluation Committee: Not Eligible This Property is associated with the Ridge Street Historic District.
County/Independent City(s):	Charlottesville (Ind. City)	
Incorporated Town(s):	No Data	
Zip Code(s):	22902, 22903	
Magisterial District(s):	No Data	
Tax Parcel(s):	290141000	
USGS Quad(s):	CHARLOTTESVILLE EAST	

Additional Property Infor	mation
Architecture Setting:	Urban
Acreage:	No Data
Site Description:	
Street and Oak Street. A sidew	y-Bailey House is located on the northwest side of Ridge Street, just south of the intersection of Ridge alk and concrete retaining wall run along the eastern end of the property, between it and Ridge Street. A the sidewalk to a walkway leading to the front porch.
Surveyor Assessment:	
them makes the remaining one	d Victorian residence is typical of the houses built on Ridge Street in the 1890s. The loss of many of s more important. This little second story porch, which has retained its Eastlake trim, is especially the of the three surviving servants quarters in the Ridge Street Historic District. The Gianniny-Bailey tscape and the District.
to E. M. Buck in 1897 (DB 8-3 Birch bought the house from A Depression (DB 69-52, 86-128	ed this lot in 1895 (City DB 6-13) and built the house the same year, according to tax records. He sold it (31), then bought it back in 1901 (DB 12-103), and sold it to c. s. Apple in 1906 (DB 17-336). Ida L. pple in 1915 (DB 27-487). Her husband, who had inherited it from her (WB 2-229), lost it during the ). E. I. and Mollie F. Bing owned it from 1935 to 1940, when they sold it to G.C. Bailey (DB 102-334), or 22 years before selling it to Mrs. Lottie Scott in 1962. The weatherboarding was covered with stucco 362.
DHR Staff 2020: This building	is a contributing resource to the Ridge Street Historic District.
Surveyor Recommendation:	Recommended Not Eligible
Ownership	
<b>Ownership Category</b> Private	Ownership Entity No Data

### **Primary Resource Information**

<b>Resource Category:</b>	Domestic
Resource Type:	Single Dwelling
NR Resource Type:	Building
Historic District Status:	Contributing
Date of Construction:	Ca 1895
Date Source:	Written Data
Historic Time Period:	Reconstruction and Growth (1866 - 1916)
Historic Context(s):	Architecture/Community Planning, Domestic
Other ID Number:	No Data
Architectural Style:	Victorian, Queen Anne
Form:	No Data

#### Virginia Department of Historic Resources Architectural Survey Form

Number of Stories:	2.0
Condition:	Good
Threats to Resource:	None Known
Cultural Affiliations:	No Data
Cultural Affiliation Details:	

No Data

#### **Architectural Description:**

1982: frame (stucco covered weatherboard); 2 storey; 2 bays; high pitched hip roof with pedimented gables over 3 projecting bays; one storey veranda on north bay. Victorian Vernacular. 1895.

1980-1994: This house is two storeys tall, three bays wide, and double pile, on a low foundation. The original weatherboarding has been covered with stucco, significantly altering the appearance of the house. The trim is painted green. There is a semi-octagonal projecting side bay on the facade, a rectangular projecting bay on the north side, and a projecting pavilion at the rear. The high-pitched hipped roof has steep pedimented gables over the three projecting bays and another centered over the southern elevation. It is covered with standing seam metal, painted red, and has Philadelphia gutters, projecting eaves and verges, and a boxed cornice. Corner brackets with a sunburst motif support the overhanging corners of the gable over the semi-octagonal bay. The sunburst motif is repeated at the peaks of the gables. The rear gable is weatherboarded; the other three are covered with pressed tin. There is a pair of 9-over-9 light tinted glass attic windows in the gable on the facade, and a single plain 1-over-1 light window in each of the others. There are two interior capped chimneys. Windows are double-sash with architrave trim, 1-over-1 light on the facade and 2-over-2 light elsewhere. The one on the veranda has a paneled spandrel, suggesting that it may originally have been a triple sash window. A deep one-storey verandah covers the northern bay of the facade and wraps around the corner to a side entrance in the projecting bay on the north side. It has a medium-pitched truncated hipped roof covered with standing-seam metal with boxed cornice. The original spool frieze and simple balustrade are gone, square posts have replaced the attenuated Eastlake posts and brackets, and the floor and steps have been replaced with concrete. The wide entrance door in the northern bay has nine lights over three panels and a three-light rectangular transom. Beside the door there is a small double-sash window with one large light bordered by small lights. A small second storey porch is set on the roof of the verandah at mindowsil

January 1994

#### **Exterior Components**

<b>Component</b> Chimneys Structural System and Exterior Treatment	<b>Component Type</b> Interior Central Wood Frame	<b>Material</b> Brick Wood	<b>Material Treatment</b> Corbeled Weatherboard
Roof Windows	Complex Double-hung	Metal Wood	No Data No Data
Porch	Wrap-Around	No Data	Posts
Foundation	Solid/Continuous	Stucco	No Data

#### **Secondary Resource Information**

#### **Historic District Information**

Historic District Name: Local Historic District Name:	Ridge Street Historic District No Data
Historic District Significance:	Ridge Street Historic District has been listed in the National Register of Historic Places since 1982 as a part of the Charlottesville Multiple Resource Area form, which recorded much of the city's historic architecture. An administrative error left the district off the Virginia Landmarks Register, but interest in state rehabilitation tax credits prompted city officials to seek designation in 2003. The residential district occupies four blocks just south of downtown and contains historic structures dating from the mid-1800s through the 1890s. Its ridge-top location attracted wealthy families who built stately Victorian-style houses there. The Ridge Street neighborhood was integrated even before the Civil War. A free black man owned property there as early as 1842 and, when the street was extended, its southern end was one of the city's most fashionable African American neighborhoods. The district is relatively unchanged and remains a cohesive black community.


#### **CRM Events**

**Event Type: DHR Evaluation Committee: Not Eligible** 

#### Virginia Department of Historic Resources Architectural Survey Form

DHR ID:	104-0025-0019
Staff Name:	DHR Evaluation Committee
Event Date:	5/1/2003
Staff Comment	
This resource, a contributing bu	ge St. Charlottesville, Tax Act File Number 2003-072, DHR File Number 104-0025-0019. ilding in the Charlottesville-Ridge Street Multiple Resource Area, was evaluated as locally significant under committee recommends that the resource is not eligible for listing with 28 points.
The committee encourages the presented for VLR listing.	applicant to pursue a district nomination, especially as such a nomination is already in place, and has never been
Event Type: Rehabilitation Ta	ax Credit
DHR ID:	104-0025-0019
Staff Name:	DHR
Event Date:	4/11/2003
Staff Comment	
Denied - Tax Act File No. 2003	-072
Event Type: Survey:Phase I/R	econnaissance
<b>Project Review File Number:</b>	No Data
Investigator:	Eugenia Bibb/Susan Smead
Organization/Company:	City of Charlottesville
Photographic Media:	Film
Survey Date:	1/1/1994
Dhr Library Report Number:	No Data
Project Staff/Notes:	
Neg #13471, fr 11/14 - Jan 199 Original survey by Eugenia Bib	
Event Type: Survey:Phase I/R	econnaissance
Project Review File Number:	No Data
Investigator:	Susan Smead & Eugenia Bibb
Organization/Company:	DHR
Photographic Media:	Digital
Survey Date:	1/1/1994
Dhr Library Report Number:	No Data
Project Staff/Notes:	
No Data	
Project Bibliographic Information	n:
DHR Staff 2020: Data based or	
	· · · · · · · · · · · · · · · · · · ·
Bibliographic Information	
Bibliography:	
No Data	
Property Notes:	
No Data	


No Data




Painted wood siding applied to 2x4 framed wall with bead-board applied on interior. Siding appears original, with some lower sections replaced with cedar siding. Trim, soffit and cornice appear original, but cannot determine; minor repairs evident. Wall studs, sill beam, upper plate, ceiling joists, and roof rafters appears original, with several areas of visible termite damage. Ceiling joists have nail patterns consistent with a simple ceiling, possible heavy paper or thin paneling. Plywood flooring over wood floor joists, of which several are modern. Structure set on stacked brick piers.

Door and windows appear original; in poor condition, but salvageable.

Where it remains, skipped board sheathing on roof rafters appears original; but in poor condition. Original roof no longer extant. Currently plywood sheathing with wood shakes and metal drip edge. Ridgeline is sagging in center. Leaks are evident, especially at the chimney.






Approximate Not to scale




This house has one of the three surviving servants' quarters in the Ridge Street Historic District. The Gianniny-Bailey House is important to the streetscape and the District.




1-storey, gable roof, white weatherboarded prob I mon









1920 Sanborn Map








c1965 Sanborn Map





























































































ADC District or IPP



Board of Architectural Review (BAR) Certificate of Appropriateness ADC Districts and IPPs Please Return To: City of Charlottesville Department of Neighborhood Development Services P.O. Box 911, City Hall Staff contacts: Charlottesville, Virginia 22902 Jeff Werner wernerjb@charlottesville.gov Telephone (434) 970-3130

Please submit the signed application form and a digital copy of submittal and attachments (via email or thumb drive). Please include application fee as follows: New construction project \$375; Demolition of a contributing structure \$375; Appeal of BAR decision \$125; Additions and other projects requiring BAR approval \$125; Administrative approval \$100. Make checks payable to the City of Charlottesville. The BAR meets the third Tuesday of the month.

Deadline for submittals is Tuesday 3 weeks prior to next BAR meeting by 3:30 p.m.

Owner Name_Clayton & Kimberly Lauter A	Applicant Name (owner)
Project Name/DescriptionDemo shed/cottage	Parcel Number 290141000
Project Property Address 507 Ridge Street	
Applicant Information         Address:       507 Ridge Street         Charlottesville, 22902         Email:       clayt.lauter@aya.yale.edu         Phone: (W)       (C)         Property Owner Information (if not applicant)	Signature of Applicant         I hereby attest that the information I have provided is, to the best of my knowledge, correct.         Signature         One         C) My + Lwster         Io         Print Name
Address: Email: Phone: (W)(C)	Property Owner Permission (if not applicant) I have read this application and hereby give my consent to its submission.
-	Signature Date
Do you intend to apply for Federal or State Tax Credits for this project?	Print Name Date
Description of Proposed Work (attach separate narrative Demolition of approx. 8' x 10' framed shed/cottage in rear List All Attachments (see reverse side for submittal rec	r yard.
For Office Use Only	Approved/Disapproved by:
Received by:	Date:
Fee paid:Cash/Ck. #	Conditions of approval:
Date Received:	

Revised 2016



HISTORIC DISTRICT ORDINANCE: You can review the *Historical Preservation and Architectural Design Control Overlay Districts* regulations in the City of Charlottesville Zoning Ordinance starting with Section 34-271 online at **charlottesville.gov** or at Municode.com for the City of Charlottesville.

DESIGN REVIEW GUIDELINES: Please refer to the current ADC Districts Design Guidelines online at chariottesville.gov

SUBMITTAL REQUIREMENTS: The following information and exhibits shall be submitted along with each application for Certificate of Appropriateness, per Sec. 34-282 (d) in the City of Charlottesville Zoning Ordinance.

(1) Detailed and clear depictions of any proposed changes in the exterior features of the subject property;

(2) Photographs of the subject property and photographs of the buildings on contiguous properties;

(3) One set of samples to show the nature, texture and color of materials proposed;

(4) The history of an existing building or structure, if requested;

(5) For new construction and projects proposing expansion of the footprint of an existing building: a threedimensional model (in physical or digital form);

(6) In the case of a demolition request where structural integrity is at issue, the applicant shall provide a structural evaluation and cost estimates for rehabilitation, prepared by a professional engineer, unless waived by the BAR.

APPEALS: Following a denial the applicant, the director of neighborhood development services, or any aggrieved person may appeal the decision to the city council, by filing a written notice of appeal within ten (10) working days of the date of the decision. Per Sec. 34-286. - City council appeals, an applicant shall set forth, in writing, the grounds for an appeal, including the procedure(s) or standard(s) alleged to have been violated or misapplied by the BAR, and/or any additional information, factors or opinions he or she deems relevant to the application.

## CHARLOTTESVILLE ARCHITECTURAL DESIGN CONTROL DISTRICTS DESIGN GUIDELINES

Chapter 1 Introduction (Part 1)

2

http://weblink.charlottesville.org/public/0/edoc/793062/2\_Introduction%20I\_BAR.pdf

Chapter 1 Introduction (Part 2)

http://weblink.charlottesville.org/public/0/edoc/793063/1\_Introduction%20II\_BAR.pdf

Chapter 2 Site Design and Elements

http://weblink.charlottesville.org/public/0/edoc/793064/3\_Chapter%20II%20Site%20Design%20and%20Elements\_BAR.pdf

Chapter 3 New Construction and Additions

http://weblink.charlottesville.org/public/0/edoc/793065/4\_Chapter%20III%20New%20Construction%20and%20Additions\_BAR.pdf

Chapter 4 Rehabilitation

http://weblink.charlottesville.org/public/0/edoc/793066/5\_Chapter%20IV%20Rehabilitation\_BAR.pdf

Chapter 5 Signs, Awnings, Vending, and Cafes

http://weblink.charlottesville.org/public/0/edoc/793067/6\_Chapter%20V%20Signs%20Awnings%20Vending%20and%20Cafes\_BAR.pdf

Chapter 6 Public Improvements

http://weblink.charlottesville.org/public/0/edoc/793068/7\_Chapter%20VI%20Public%20Improvements\_BAR.pdf

**Chapter 7 Moving and Demolition** 

http://weblink.charlottesville.org/public/0/edoc/793069/8\_Chapter%20VII%20Moving%20and%20Demolition\_BAR.pdf

507 Ridge Street 9. s. servante collage: City survey 1994 1-storey, gable roof, white weatherboarded prob I non 

Certificate of Appropriateness BAR # 22-11-05 914 Rugby Road. TMP 50145000 Rugby Road Historic Conservation District Owner: Erin and George Sloane Applicant: John Voight / JKV Architects Project: Alterations to front porch, side addition

Application components (please click each link to go directly to PDF page):

- Staff Report
- Historic Survey
- Application Submittal

City of Charlottesville Board of Architectural Review Staff Report November 15, 2022



## **Certificate of Appropriateness Application (HC District)** 914 Rugby Road. TMP 50145000

Rugby Road HC District Owner: Erin and George Sloane Applicant: John Voight / JKV Architects Project: Alterations and side addition



## **Background**

Year Built:c1921District:Rugby Road Historic Conservation DistrictStatus:Contributing

## **Prior BAR Review**

N/A

## **Application**

• Submittal: JKV Architects drawings 914 Rugby Road, dated October 26, 2022: Sheets A-1, A-2, A-3, and A-4.

Request CoA for construction of a single story, side addition (replacing the exist two-story 1980s addition) and reconstruction of the front porch (replacing c1980s alterations). <u>Note</u>: The rear portion of the addition is not visible from Rugby Road and therefore exempt from BAR review.

## **Discussion and Recommendations**

Note: The regulations and design guidelines for projects within a Historic Conservation District (HCD) are intentionally less rigid than those for an ADC District. The HCD designations are intended to preserve the character-defining elements of the neighborhoods and to assure new construction is not inappropriate to that character, while minimally imposing on residents who may want to upgrade their homes. Even for a HCD property that might qualify for the more-rigid designation, in evaluating the proposal the BAR may only apply the HCD requirements and guidelines.

See staff comments below regarding the proposed roof style. (Building Form – roofs and porches.)

Staff recommends either BAR approval [per the recommended motion below] or, should the BAR request modifications to the design, by direction to staff allow the subsequent review to be administrative. (Per City Code Sec. 34-346, an administrative review is allowed: a) with BAR authorization, for requests previously reviewed by the BAR; and b) for minor accessory buildings or additions, after consultation with the chair of the BAR.)

## **Suggested Motions**

*Approval*: Having considered the standards set forth within the City Code, including City Design Guidelines for Historic Conservation Districts, I move to find that the proposed side addition and front porch alterations at 914 Rugby Road satisfy the BAR's criteria and are compatible with this property and other properties in the Rugby Road Historic Conservation District, and that the BAR approves the application [as submitted].

[...as submitted with the following conditions: ...].

## Criteria, Standards, and Guidelines

## **Review Criteria Generally**

Sec. 34-341 of the City Code. Criteria for approval

- a. In considering a particular application the BAR shall approve the application unless it finds:
  - 1. That the proposal does not meet specific standards set forth within this division or applicable provisions of the\_conservation district design guidelines; and
  - 2. The proposal is incompatible with the historic, cultural or architectural character of the conservation district in which the property is located.
- b. The BAR's review of the proposed new construction or addition to a building or structure shall be limited to factors specified in section 34-342. The BAR's review of the proposed demolition, razing or moving of any contributing structure shall be limited to the factors specified in section 34-343.
- c. The BAR, or city council on appeal, may require conditions of approval as are necessary or desirable to ensure that any new construction or addition would be compatible with the scale and character of the historic conservation district. Prior to attaching conditions to an approval, due consideration shall be given to the cost of compliance with the proposed conditions.

<u>Sec. 34-342 of the City Code</u>. Standards for review of new construction and additions. The following features and factors shall be considered in determining the appropriateness of proposed new construction and additions to buildings or structures:

- 1) Whether the form, height, scale, mass and placement of the proposed construction are visually and architecturally compatible with the site and the applicable conservation district;
- 2) The harmony of the proposed changes in terms of overall proportion and the size and placement of entrances and windows;
- 3) The impact of the proposed change on the essential architectural form and integrity of the existing building;

- 4) The effect, with respect to architectural considerations, of the proposed change on the conservation district neighborhood;
- 5) Any applicable provisions of the city's conservation district design guidelines.

## Pertinent Design Review Guidelines for New Construction and Additions

Building Location - setback and spacing

- 1. Align a new building close to the average building setback line on the same street, if established, or consistent with the surrounding area.
- 2. Maintain average spacing between buildings on the same street.

**Staff Comment**: The side addition replaces and existing porch and will not conflict with the typical spacing within the district.

## Building Scale - height and massing

- 1. Keep the footprint, and massing of new buildings consistent with the neighborhood characteristics and compatible with the character of buildings on the same street.
- 2. Keep the height and width of new buildings within the prevailing average height and width. Exceptions up to 200% of the prevailing height and width may be approved by the BAR when contextually appropriate.
- An addition needs to be perceived as an addition and therefore should not visually overpower the existing building in scale and design.
   [...]

**Staff Comment**: The addition is compatible with the scale and design of the existing house; the proposed materials, siding, and roof design differentiate the new from the existing. (Re: roof, see staff comment below.)

## Building Form – roofs and porches

- 1. Roof forms should reference contributing buildings on the same street or surrounding area. Other roof forms may be approved by the BAR when contextually appropriate.
- 2. If many of the contributing buildings on the same street have porches, then it is strongly recommended that the design of a new residence includes a porch or similar form of similar width and depth.

**Staff Comment:** Of the 30+ properties in this district, there is no typical style or material for existing roofs in the district. (See attached images.) The BAR should discuss if the proposed mansard-style roof is compatible with the existing house and the district. (See staff comment above.)

## Building Openings - orientation, doors and windows

- 1. A single entrance door (or main entrance of a multifamily dwelling) facing the street is recommended.
- 2. Window and door patterns and the ratio of solids (wall area) to voids (window and door area) of new buildings should be compatible with contributing buildings in the surrounding area.
- 3. Windows should be simple shapes compatible with those on contributing buildings, which are generally vertically oriented in residential areas.

**Staff Comment**: The scale, design, and locations of the addition windows are consistent with the existing house.

## **Building Materials and Textures**

- 1. The selection of materials and textures for a new building should relate architecturally to the district, and should be compatible with and complementary to neighboring buildings.
- 2. Long-lasting, durable and natural materials are preferred, including brick, wood, stucco, and cementitious siding and standing seam metal roofs. Clear glass windows (VLT of 70% or more) are preferred.

**Staff Comment**: The proposed materials are consistent with the district. Brick, copper, wood and Boral trim and siding, and FRP columns. (The BAR has previously approved the use of Boral FRP materials.)

## **Building Paint**

1. Painting unpainted brick or other masonry is discouraged because it is irreversible and may cause moisture problems.

Staff Comment: Brick repairs to the north (side) will be painted to match the existing masonry.


## <u>Site</u>


1. Fences or walls that abut a City street (or fences located in a side yard between a street and the front of the principal structure on a lot) should not exceed three and one-half feet in height.

## Staff Comment: n/a


Rugby Road Historic Conservation District adopted September 2, 2014: Architectural character-defining features:


- 1.5, 2.0, or 2.5 story dwellings with stucco, red brick or painted brick, or wood siding,
- Front porticos or porches
- Slate shingle roofs, gable or hipped roof forms, roof dormers,
- Contributing outbuildings, and deep-set, planted front yards mostly unpaved with no visible garages.






$\left  \frac{1}{2} \right $																								
2																								
ם																								
2																								
2																								
2																								
2																								
[Ц []																								
2																								
וטן הו																								
2																								
2																								
2																								
2																								
		╝┍┛				┘∟		니			-1	-	·	·  '				- 1			-	·		





(3)






# WEST SIDE OF HOUSE FROM RUGBY ROAD



# FRONT PORCH DETAIL



914 Rugby Road

Charlottesville, Va

October 26, 2022

JKV

ARCHITECTS

Charlottesville, Virginia

434.825.3888

 $\ensuremath{\mathbb{C}}$  Copyright John K. Voight Architects. All rights reserved 2022

REVISIONS/SUBMISSIONS:

616 Rugby Road (1921)



703 Rugby Road (1910)



712 Rugby Road (1925)





## 700 Rugby Road (1921)

**Rugby Road HC District** — Dwellings (*contributing structures*)

714 Rugby Road (1906)



803 Rugby Road (1917)



**804 Rugby Road** (1907)





**807 Rugby Road** (1929)



**809 Rugby Road** (1929)



**1801 Rugby Place** (1929)



**810 Rugby Road** (1923)



**900 Rugby Road** (1899)



**914 Rugby Road** (1921)



**910 Rugby Road** (1925)



915 Rugby Road (1929)



Rugby Road HC District — Dwellings (contributing structures)917 Rugby Road (1929)



**919 Rugby Road** (1921)











**Rugby Road HC District** — Dwellings (*contributing structures*)

**924 Rugby Road** (1908)



**929 Rugby Road** (1929)



928 Rugby Road

(1922)

**933 Rugby Road** (1929)





## **936 Rugby Road** (1911)







**614 Rugby Road** (1920)



### 914 Rugby Road



### Date: 1921 ca. (not on 1920 Sanborn map) District Status: Contributing Resources: 1 Single Dwelling (c); 1 Garage (c); 1 pool (c) Style: Colonial Revival

**Architectural Description:** The side-gabled, 2.5-story, stretcher-bond brick veneer dwelling stands three bays wide and two bays deep. Symmetrically fenestrated, the facade features a central entrance flanked by 6/6 wood windows. The entrance is sheltered by a single-bay shed-roofed porch with sturdy, paired Tuscan post supports and a molded wood cornice. A fanlight transom and sidelights details the entry. Three 6/6 wood windows pierce the second story, with the central window smaller in size. Each window features fixed louvered shutters, square-edged sills, and a thin, molded wood surround. The upper windows feature rowlock brick lintels. A molded wood cornice with returns details the asphalt-shingled roof that is pierced with three attenuated gabled dormers. Each wood-frame dormer is lit with a 6/6 window and capped by prominent pedimented gable peak with boxed cornice and closed tympanum. An exterior-end and an interior-end brick chimney each rose from the roof. A two-story shed wing was added to the north corner of the dwelling. It features vinyl siding and 6/6 wood windows. A small sunporch addition was also added to the rear elevation, which is accessed by an exterior wood stair with portico.

### Secondary Resource: Garage, ca. 1921

The one-story, brick garage dates to circa 1921. Featuring a hipped asphalt-shingle roof, the garage includes a front-gabled projection with weatherboard -clad gable peak and two roll-up, paneled-with lights doors dating to circa 1960. The garage also features a molded wood cornice and poured concrete floor.

**Pool** (1950?). An in-ground concrete pool is curvilinear in shape. It is currently empty and overgrown.

**Site Description:** Set on a narrow, .48-acre rectangular parcel, the dwelling faces Rugby Road. A circular brick driveway extends across the front of the dwelling, with a spur extending along the side to a garage. The slightly sloping property features a small, grassy lawn, mature trees and shrubs, and some foundation landscaping. A fenced rear yard features a grassy lawn and an in-ground pool. The property line to the rear is wooded.



Historic Conservation District (Martha Jefferson, Woolen Mills, Rugby Road) <u>NOTE</u>: For IPPs within HC Districts use the ADC District/IPP CoA application.



Board of Architectural Review (BAR) Conservation District - Certificate of Appropriateness Please Return To: City of Charlottesville Department of Neighborhood Development Services P.O. Box 911, City Hall Charlottesville, Virginia 22902 Telephone (434) 970-3130 Staff email: wernerjb@charlottesville.gov

Please submit the signed application form and a digital copy of submittal and attachments (via email or thumb drive).

Please include application fee as follows: New construction project \$375; Demolition of a contributing structure \$375; Appeal of BAR decision regarding new construction or demolition \$125. Make checks payable to the City of Charlottesville.

No fee required for: Additions and other projects requiring BAR approval and not listed above; Administrative approvals; Appeals of BAR decisions if the original application was not subject to an application fee. The BAR meets the third Tuesday of the month.

Deadline for submittals is Tuesday 3 weeks prior to next BAR meeting by 3:30 p.m.

Project Name/Description Addition and alterations	Parcel Number050145000
Project Address/Location914 Rugby Road	,
Owner Name_ Erin and George Sloane	Applicant NameJohn Voight / JKV Architects
Address: John Voight, JKV Architects Email:jv@johnkvoight.com Phone: (W) 434.825.3888 (H)	Signature of Applicant I hereby attest that the information I have provided is, to the best of my knowledge, correct. IUI25 2022 Signature JONN VOIGNT IUI25 2022
Property Owner Information (if not applicant)	Print Name Date
Address:914 Rugby Rd, Cville, 22903	Property Owner Permission (if not applicant) I have read this application and hereby give my consent to its submission. SEE EMAIL FROM OWNER
	Signature Date
	Print Name Date

Description of Proposed Work (attach separate narrative if necessary):\_

Alterations to front porch and north (side) addition. Per JKV Architect drawings for 914 Rugby Road, dated Oct 6, 2021: Sheets D1.1, A1.2, A1.3, A2.1, A2.2, and A2.3.

List All Attachments (see reverse side for submittal requirements):

For Office Use Only	Approved/Disapproved by:
Received by:	Date:
Fee paid:Cash/Ck. #	Conditions of approval:
Date Received:	
Revised April 2017	

P22 A112

## **Certificate of Appropriateness**

Preliminary Discussion (No action to be taken) 300 Court Square, TMP 530096100 North Downtown ADC District Owner: Eagle Tavern, LLC Applicant: Candace DeLoach, Claudine Wispelwey Project: Exterior alterations

## Application components (please click each link to go directly to PDF page):

- Staff Report
- Historic Survey
- Application Submittal

**City of Charlottesville Board of Architectural Review Staff Report** November 15, 2022

## **Certificate of Appropriateness Application**

Preliminary Discussion (No action to be taken) 300 Court Square, TMP 530096100 North Downtown ADC District Owner: Eagle Tavern, LLC Applicant: Candace DeLoach, Claudine Wispelwey Project: Exterior alterations





## Background:

Year Built:Farish House 1854; Annex (south wing) c1880.District:North Downtown ADC DistrictStatus:Contributing

## **Prior BAR Reviews**

n/a

## **Application**

- Attachments:
  - Site history and project narrative
  - o Photos
  - $\circ$  Renderings
  - o Historic Surveys

Preliminary discussion of planned exterior rehabilitation and alterations. Applicant seeks input prior to preparing a formal submittal.

## **Discussion**

This is a preliminary discussion, no BAR action is required; however, by consensus, the BAR may express an opinion about the project as presented. (For example, the BAR might express consensus support for elements of the project, such as its scale and massing.) Such comments will not

constitute a formal motion and the result will have no legal bearing, nor will it represent an incremental decision on the required CoA.

There are two key objectives of a preliminary discussion: <u>Introduce the project to the BAR; and</u> <u>allow the applicant and the BAR to establish what is necessary for a successful final submittal</u>. That is, a final submittal that is complete and provides the information necessary for the BAR to evaluate the project using the ADC District Design Guidelines and related review criteria.


In response to any questions from the applicant and/or for any recommendations to the applicant, the BAR should rely on the germane sections of the ADC District Design Guidelines and related review criteria. While elements of other chapters may be relevant, staff recommends that the BAR refer to the criteria in Chapter IV—*Rehabilitation*. (Link: <u>Chapter 4 Rehabilitation</u>)

## From the ADC District Design Guidelines - Introduction

Chapter 1 Introduction (Part 1) and Chapter 1 Introduction (Part 2)

- North Downtown ADC District: Adjacent to the Albemarle County Courthouse and laid out according to the 1762 town grid, this area served as the city's first civic, religious, and commercial center. Thomas Jefferson, James Monroe and James Madison were frequent visitors to the Court Square area. Park Street residences built in the late eighteenth century for lawyers, judges and other professionals still retain their architectural integrity. Today, this district represents the socio-economic and architectural evolution of the original town.
- *Subarea* c. <u>Court Square:</u> historic core, small scale, brick, row houses, gable roofs, simple designs, limited setback, 2 stories, limited plantings.

Most of the buildings in Subarea C were constructed prior to 1900. Over half, including the *Farish House*, were built prior to 1860.



## **Suggested Motions**

No action to be taken.

## Criteria, Standards, and Guidelines

## **Review Criteria Generally**

Sec. 34-284(b) of the City Code states that, in considering a particular application the BAR shall approve the application unless it finds:

- (1) That the proposal does not meet specific standards set forth within this division or applicable provisions of the Design Guidelines established by the board pursuant to Sec. 34-288(6); and
- (2) The proposal is incompatible with the historic, cultural or architectural character of the district in which the property is located or the protected property that is the subject of the application.

## Pertinent Standards for Review of Construction and Alterations include:

- (1) Whether the material, texture, color, height, scale, mass and placement of the proposed addition, modification or construction are visually and architecturally compatible with the site and the applicable design control district;
- (2) The harmony of the proposed change in terms of overall proportion and the size and placement of entrances, windows, awnings, exterior stairs and signs;
- (3) The Secretary of the Interior Standards for Rehabilitation set forth within the Code of Federal Regulations (36 C.F.R. §67.7(b)), as may be relevant;
- (4) The effect of the proposed change on the historic district neighborhood;
- (5) The impact of the proposed change on other protected features on the property, such as gardens, landscaping, fences, walls and walks;
- (6) Whether the proposed method of construction, renovation or restoration could have an adverse impact on the structure or site, or adjacent buildings or structures;
- (7) Any applicable provisions of the City's Design Guidelines.

## **Pertinent ADC District Design Guidelines**

Chapter 4 Rehabilitation

The Zebra Carriage Hotel A Luxury Boutique Hotel 300 Court Square, Charlottesville Virginia BAR Submittal for review on November 15, 2022

# **COURT SQUARE HISTORY**

The original 300 Court Square building was a simple wooden framed building constructed around 1791 and housed The Eagle Tavern. The Eagle Tavern could seat 200 patrons. William P. Farish had already developed a stagecoach line in 1845 when he purchased the property and erected the current building in 1854. The Farish House Hotel soon thereafter became a major stagecoach stop. After the Civil War, federal occupying forces used it as a headquarters for two years. 300 Court Square has long been used as a gathering spot on court day for food and rest. Travelling peddlers sold products along the porch on monthly court days. Public dances and celebrations echoed through the large parlor halls. Operating as a hotel, also under the name, The Colonial Hotel, until the 1960's, 300 Court Square was later converted into offices and apartments.





PHOTO OF BUILDING AS IT EXIST CURRENTLY



HOLSINGER'S 1915 PHOTOGRAPH

Historic Court Square has long been the center of Charlottesville. The City's courthouse has been in continuous use for over 200 years and is one of America's most historic. No other courthouse has been used by three early American Presidents at the same time. Local elections were held here, and the County Court conducted business with the help of young attorneys and magistrates such as Thomas Jefferson and James Monroe. Mr. Jefferson and Mr. Monroe, along with James Madison later became Presidents and could at times be seen here together.



ARCHITECT'S RENDERING OF BUILDING

#### <u>300 Court Square – Front of building, North-Facing</u>

- Replace and relocate center windows on balconies with custom doors resembling original windows to allow guest access to balconies. Original windows will be used in other parts of the building.
- Remove four smaller windows, investigations point to these windows as not original, infill with brick. Remaining windows will be centered and symmetrical.
- Repair and repoint all areas of failing brick examples of matching brick to be shown in meeting.
- Whitewash brick to conceal brick and mortar variation and to blend years and years of variating mortar repairs. Please see photos of both buildings having been painted white (photos 1, 2A, 2B)
- Brick is failing in many places, requesting ability to use a lime mortar sealant to stabilize the brick (photos 3-7, 9A, 9B &10).
- Install operable paneled shutters to match Zero Court Square's shutters on the North and East sides of the building (photos 11A, 11B, 12A & 12B)
- Install original historic 9' tall doors with upper true divided light panels doors were found in the building. (photo 13)
- Install original historic 9' tall six-paneled outer doors to be propped open doors were in building. (photo 14)
- Doors, shutters, and trim to be painted "Green-Blue" No BS16D45 by Fine Paints of Europe. Please see sample on actual building.
- Paint downspouts antiqued copper color
- Balcony ceilings to be painted Dolphin Cove 722 Benjamin Moore. Please see sample on building.
- Install four handmade copper gas lanterns flanking windows: French Quarter Lantern by Bevelo. (photo 15)
- Install three handmade copper gas lantern pendants on the two balconies and above the front entry door. (photo 16)
- Install four flush-mounted landscape lights in sidewalk to up-light plantings and illuminate pilaster detail
- Install four low-watt down lights to illuminate top of pilasters
- "THE ZEBRA CARRIAGE HOTEL" to be painted in black lettering on front top cornice
- Signage is a vintage steel bracket and sign. (photo 17)
- Install black and white canvas awning with Greek Key pattern that extends from door to street. Awning is supported by copper poles and illuminated from within
- Install three flag poles for alternating flags
- Remove existing exterior modern storm windows nearly all are not functioning properly and have been compromised

#### **East Side of building – 6th Street**

- Install two-story columned portico to match the original one-story portico.
- Portico will surround existing fire escape and continue to serve as an emergency egress. (See photo 10).
- Portico railing to have zig-zag wood railing similar to "The Second Yard" on Market Street (photo 18)
- Install brick handicap ramp that extends from the corner of building to the portico.
- Remove door and steps to right of entry door (photo 19) and replace with historic window that matches the original window (photo 20 of original window)

- Install new single 15 light wood entry door with true divide lights to replace non-functioning double doors. (photo 22)
- Eagle Tavern sign to hang by this entrance
- Replace solid wood doors and sidelights (originally widows) with a single true divided light door to look like windows. These doors will provide emergency egress
- Install a handmade copper lantern on each level of portico. (photo 16)
- A large portion of the brick wall will have to be replaced for structural reasons. (photos 3-10)
- Install wood double doors with 15 true divided light doors to gift store. (photo 23 & 24)
- All doors painted to be painted "green-blue" No BS 16D45 Fine Paints of Europe
- Gas lantern to be installed at gift store entry and at 100 Court Square entry (photo 15)

### **Rear of the building – Not Visible from 6<sup>th</sup> Street**

- Replace mismatched, un-original windows with matching windows
- A glass and wood door to match the windows will be installed in the center for emergency egress and to access the deck. (photo 24 & 25)
- A two-story trellised wall will be built against the neighboring equipment building to hide the AC chiller on top. (photo 26)
- A wooden deck will be built to the same level as the first-floor ballroom. (photo 26)
- An arbor will be built over head to screen the huge amount of satellite dishes on the roof of the 29 building. This is a major eyesore and a big obstacle to overcome. (photos 27, 28 & 29)
- A retractable glass roof will be installed just below the eves so events can occur during inclement weather.
- A two-story stone chimney will be the focal point of the terrace and act to screen the satellite dishes (photo 26)
- The small widow on the annex building that doesn't match the others will be replaced with a 15 light glass door to allow for emergency egress and handicap access to the annex from the main building.
- Windows on the 2nd and 3rd floors will have Bermuda Shutters to obscure the view (photo 26, 30)



PHOTO SHOWING THREE OF THE ADDED WINDOWS (PHOTO 20) AND THE ORIGINAL PORTICO






PHOTO 1 – HISTORIC PHOTO OF 6<sup>TH</sup> STREET SIDE OF BUILDING HAVING BEEN PAINTED WHITE





PHOTO 2A & 2B – HISTORIC PHOTOS OF BUILDING EXTERIOR HAVING BEEN PAINTED WHITE



PHOTO 3 – FAILING BRICK CONDITION



```
PHOTO 4 – FAILING BRICK CONDITION
```




PHOTO 5 – FAILING BRICK




PHOTO 6 - MANY VARIATIONS OF MORTAR AND BRICKS - REPAIRS OVER THE YEARS





PHOTO 7 – VARIATIONS OF MORTAR AND BRICK – POOR REPAIR WORK



PHOTOS 9A & 9B – BRICK DETERIORATION ACTUAL CONDITIONS






PHOTO 10 – FAILING BRICK AT STREET LEVEL, FIRE ESCAPE TO BE WRAPPED BY PORTICO



PHOTO 11A - SHUTTERS ON ZERO COURT SQUARE, CHARLOTTESVILLE. DIRECTLY ACROSS FROM 300 COURT SQUARE



PHOTO 11B – PANELED SHUTTERS ON ZERO COURT SQUARE



```
PHOTO 12 A – ORIGINAL SHUTTER PINS
```




PHOTO 12 B – ORIGINAL SHUTTER PINS



PHOTO 13 – GLASS FRONT ENTRY DOORS – FOUND IN THE BUILDING




PHOTO 14 - EXTERIOR FRONT DOORS TO STAY OPEN



PHOTO 15 – WALL MOUNTED GAS LANTERN – "FRENCH QUARTER" BY BEVELO





PHOTO 17 – HISTORIC STEEL SIGN TO BE HUNG WEST OF FRONT ENTRY DOORS






PHOTO 18 - SCISSOR RAILING TO BE USED ON PORTICO - THE SECOND YARD ON MARKET STREET



PHOTO 19 – REMOVE DOOR AND STEPS TO RIGHT OF PORTICO – REPLACE WITH ORIGINAL WINDOW



PHOTO 20 - ORIGINAL PORTICO AND ORIGINAL WINDOW TO NORTH OF PORTICO






PHOTO 22 – NON FUNCTIONING DOUBLE DOORS TO BE REPLACED WITH 15 LIGHT DOOR TO MATCH WINDOWS



PHOTO 23 - EXISTING 6<sup>TH</sup> STREET DOOR TO FUTURE GIFT STORE – TO BE REMOVED AND REPLACED WITH 15-LIGHT DOUBLE DOORS SHOWN BELOW



PHOTO 24 - DOORS TO BE USED FOR ENTRY TO GIFT STORE ON 6<sup>TH</sup> STREET AND FROM BALLROOM TO TERRACE



PHOTO 25 - NEW FRENCH DOORS TO BE LOCATED BETWEEN LOWER WINDOWS.

DECK ADDED AT LEVEL OF THE DOORS



PHOTO 27 - VIEW OF SATELLITE DISHES FROM SOUTH FACING WINDOWS



PHOTO 28 - VIEW OF SATELLITE DISHES FROM COURTYARD – TERRACE ESSENTIAL TO BLOCK THESE EYESORES



PHOTO 29 - VIEW OF AC CHILLER FROM "ANNEX ROOMS"



PHOTO 26 - DECK WITH ARBOR AND TRELLIS TO BE BUILT TO OBSURE SATELLITE DISHES AND AC CHILLER




PHOTO 30 - BERMUDA SHUTTERS ON BACK OF BUILDING - NECESSARY TO BLOCK VIEWS OF SATELLITE DISHES

## 300 Court Square - BAR discussion Nov 15, 2022



300 Court Square - BAR discussion Nov 15, 2022





# 300 Court Square - BAR discussion Nov 15, 2022





300 Court Square - BAR discussion Nov 15, 2022











6th St. NE





# SURVEY

BASE DATA

NOTE .

1976 SURVEY

IDENTIFI	CATION
----------	--------


Street Address:	500 East Jefferson Street	Historic Name:	The Farish House
Map and Parcel:	53-96.1	Date/Period:	1854
Census Track & Bl	ock: 1-112	Style:	Greek Revival
Present Owner: Address:	Joseph T. Norris Box 591, City	Height to Cornice: Height in Stories:	3
Present Use: Original Owner:	Offices and Hotel Annes George L. Peyton	Present Zoning: Land Area (sq.ft.):	B-3 72 x 116
Original Use:	Hotel	Assessed Value (land	+ imp.): 20,380 + 21,270 = 41,650

# ARCHITECTURAL DESCRIPTION

The Farish House is an example of the Greek Revival style of architecture which characterized buildings of the 1850's. The structure is three stories high with a recessed pavilion providing a sheltered entrance. The pilasters are used to define and elaborate these changes in the wall plain. The capitals of the pilasters are formed out of molded brick, a refinement not seen at the Levy Opera House or the Abell-Gleason House. Typically, the windows are treated with paneled spandrels. The walls are constructed of American bond (i.e. all streachers) brickwork, one of the first examples found in the city.

# HISTORICAL DESCRIPTION

The site upon which the Farish House stands has always been used for public entertainment. Benjamin Brown and David Ross bought the lot from Thomas Walker and built the Eagle Tavern on this site prior to 1791. It was a typical eighteenth century tavern with a wide front veranda and four chimneys. The fate of the tavern is not known, but the existing structure is stylistically datable from the mid 1850's. When the Hotel was sold to William Farish in 1863, it was already known as the Farish House. Subsequently it has been known as the Hotel Colonial until 1925. Deed references: ACDB 47-206, 62-494, 63-489, City DB 1-309, 7-67, 11-350, 13-249, 13-331 (See Monticello Hotel for post 1924 deed references).



LANDMARK COMMISSION-DEPARTMENT OF COMMUNITY DEVELOPMENT


	HISTORIC	VIRGINIA LANDMARKS SURVEY FORM	COMMISSION	File no. Negative no(s).
Historic name County/Town/(	City <b>AUPENA</b>	ue/CHARLOTT		
USGS Quad Original owner Original use	HARLOHESVI	LE EAST Date or Archited	period ct/builder/craftsmen	
Present owner Present owner a	address	Source o Source o Stories		
Present use Acreage		Roof ty	tion and wall const'n	
	of structure and envi threats to structure	rons FAIR	A	
	eological interest			
Architectural d	escription (Note signi	egister potential? yes ficant features of plan, s	tructural system and interio	or and exterior decoration.
taking care to p	point out aspects not	visible or clear from pho and their approximate age	otographs. Explain nature a: es, cemeteries, etc.)	nd period of all alterations
	BRICK	(7 COURS	SE AMERICA XOF. L BAV	SN BONDJ;
	CULAR	. C. 1880	NORTH	WATL
	pouts	EAGLE TAVI	ERN. ENTR	RANCEON
	NORIH	FARCE.	COLONIAL I TUTED PLAS	SERS,
	PEDMEN	T, ALIGHT	TRANSOM.	6-PANEL,
PEDMENT, 4-LIGHT TRANSDM. 6-PANEL, PLAT-PANEL DOOR, WINDOWS WEST WALL: 1/1 SASH WITH SEGHENTAL				
	ARCHES.	BOX LOR	NICE,	
Interior inspect	ted? No.		ssociated with th	ne property.)
			Z	
	71		Tii I	
TT	111			

i

Primary sources (Manuscript documentary or graphic materials; give location.)

Names and addresses of persons interviewed

Plan (Indicate locations of rooms, doorways, windows, alterations, etc.)



# **Certificate of Appropriateness**

Preliminary Discussion (No action to be taken) 204 Hartmans Mill Road, TMP 260038000 Individually Protected Property Owner: Jocelyn Johnson and William Hunt Applicant: Dan Zimmerman / Alloy Workshop Project: Addition and exterior alterations

# Application components (please click each link to go directly to PDF page):

- Staff Report
- Historic Survey
- Application Submittal

City of Charlottesville Board of Architectural Review Staff Report November 15, 2022

# **Certificate of Appropriateness**

Preliminary Discussion (No action to be taken) 204 Hartmans Mill Road, TMP 260038000 Individually Protected Property Owner: Jocelyn Johnson and William Hunt Applicant: Dan Zimmerman / Alloy Workshop Project: Addition and exterior alterations





#### **Background**

Year Built:House: c1873, with ongoing additions through 1920.District:Individually Protected Property

*George T. Nimmo House*. Family tradition holds that the original house--believed to be the northeast corner--was built in 1870, with later additions occurring over an extended period. Nimmo acquired the property in 1873 and tax records indicate three periods of building activity--1873-1874, 1880-1885, and 1915-1920. The original house likely dates to 1873. The periods of construction coincide with Census data showing the growth of the Nimmo household. (Historic Survey and Census data attached.)

# **Prior BAR Actions**

<u>September 15, 2020</u> – BAR discussed proposed demolition of the cottage. In lieu of requiring an engineer's evaluation, on September 22 four members of the BAR visited the site.

<u>October 20, 2020</u> – BAR approved CoA for demolition of the cottage. (As a condition of approval, the applicant provided staff with photos and documentation.) http://weblink.charlottesville.org/public/0/edoc/798350/2020-10\_204%20Hartmans%20Mill%20Road\_BAR.pdf

# **Application**

• Applicant's submittal: Alloy Workshop drawings *Johnson Hunt Renovations*, dated November 8, 2022: Sheets A0.0, A1.1, A1.2, and A1.3.

<u>Preliminary discussion. No action to be taken</u>. Proposed alterations to the single-story, framed house include two additions (enclosing a patio and deck), construction of two fireplaces, new windows and doors (in some locations), a screened porch, and an extension of the rear deck.



# **Discussion and Recommendations**

<u>Regarding the proposed addition</u>: During a preliminary discussion the BAR may, by consensus, express an opinion about the project as presented. (For example, the BAR might express consensus support for elements of the project, such as its scale and massing.) Such comments will not constitute a formal motion and the result will have no legal bearing, nor will it represent an incremental decision on the required CoA.

There are two key objectives of a preliminary discussion: Introduce the project to the BAR; and allow the applicant and the BAR to establish what is necessary for a successful final submittal. That is, a final submittal that is complete and provides the information necessary for the BAR to evaluate the project using the ADC District Design Guidelines and related review criteria. [Note: The ADC District guidelines are applied to IPP projects.]

In response to any questions from the applicant and/or for any recommendations to the applicant, the BAR should rely on the germane sections of the Design Guidelines and related review criteria. While elements of other chapters may be relevant, staff recommends that the BAR refer to the criteria in Chapter II--*Site Design and Elements*, Chapter III--*New Construction and Additions*, and Chapter IV—*Rehabilitation*.

As a checklist for the preliminary discussion, the criteria for Additions in Chapter III:

- Function and Size
- Location
- Design
- Replication of Style
- Materials and Features
- Attachment to Existing Building

The BAR should also consider the building elements and details necessary to evaluate the project. Renderings and schematics communicates mass, scale, design and composition; however a complete application should include details and specific information about the projects materials and components. For example:

- Measured drawings: Elevations, wall details, etc.
- Roofing: Flat, hipped, etc. Metal, slate, asphalt. Flashing details.
- Gutters/downspouts: Types, color, locations, etc.
- Foundation.
- Walls: Masonry, siding, stucco, etc.
- Soffit, cornice, siding, and trim.
- Color palette.
- Doors and windows: Type, lite arrangement, glass spec, trim details, etc.
- Porches and decks: Materials, railing and stair design, etc.
- Landscaping/hardscaping: Grading, trees, low plants, paving materials, etc.
- Lighting. Fixture cut sheets, lamping, etc.

# Suggested Motions

No action will be taken.

# Criteria, Standards, and Guidelines

# **Review Criteria Generally**

Sec. 34-284(b) of the City Code states that, in considering a particular application the BAR shall approve the application unless it finds:

- (1) That the proposal does not meet specific standards set forth within this division or applicable provisions of the Design Guidelines established by the board pursuant to Sec.34-288(6); and
- (2) The proposal is incompatible with the historic, cultural or architectural character of the district in which the property is located or the protected property that is the subject of the application.

# Pertinent Standards for Review of Construction and Alterations include:

- (1) Whether the material, texture, color, height, scale, mass and placement of the proposed addition, modification or construction are visually and architecturally compatible with the site and the applicable design control district;
- (2) The harmony of the proposed change in terms of overall proportion and the size and placement of entrances, windows, awnings, exterior stairs and signs;
- (3) The Secretary of the Interior Standards for Rehabilitation set forth within the Code of Federal Regulations (36 C.F.R. §67.7(b)), as may be relevant;
- (4) The effect of the proposed change on the historic district neighborhood;
- (5) The impact of the proposed change on other protected features on the property, such as gardens, landscaping, fences, walls and walks;
- (6) Whether the proposed method of construction, renovation or restoration could have an adverse impact on the structure or site, or adjacent buildings or structures;
- (7) Any applicable provisions of the City's Design Guidelines.

# **Pertinent ADC District Design Guidelines**

Chapter II – *Site Design and Elements* Link: Chapter 2 Site Design and Elements

- B. Plantings
- C. Walls and Fences
- D. Lighting
- E. Walkways and Driveways
- F. Parking Areas and Lots
- G. Garages, Sheds, and Other Structures
- H. Utilities and Other Site Appurtenances

Chapter III – New Construction and Additions Link: <u>Chapter 3 New Construction and Additions</u> <u>Checklist from section P. Additions</u>

- 1) Function and Size
  - a. Attempt to accommodate needed functions within the existing structure without building an addition.
  - b. Limit the size of the addition so that it does not visually overpower the existing building.
- 2) Location
  - a. Attempt to locate the addition on rear or side elevations that are not visible from the street.
  - b. If additional floors are constructed on top of a building, set the addition back from the main façade so that its visual impact is minimized.
  - c. If the addition is located on a primary elevation facing the street or if a rear addition faces a street, parking area, or an important pedestrian route, the façade of the addition should be treated under the new construction guidelines.
- 3) Design
  - a. New additions should not destroy historic materials that characterize the property.
  - b. The new work should be differentiated from the old and should be compatible with the massing, size, scale, and architectural features to protect the historic integrity of the property and its environment.

- 4) Replication of Style
  - a. A new addition should not be an exact copy of the design of the existing historic building. The design of new additions can be compatible with and respectful of existing buildings without being a mimicry of their original design.
  - b. If the new addition appears to be part of the existing building, the integrity of the original historic design is compromised and the viewer is confused over what is historic and what is new.
- 5) Materials and Features
  - a. Use materials, windows, doors, architectural detailing, roofs, and colors that are compatible with historic buildings in the district.
- 6) Attachment to Existing Building
  - a. Wherever possible, new additions or alterations to existing buildings should be done in such a manner that, if such additions or alterations were to be removed in the future, the essential form and integrity of the buildings would be unimpaired.
  - b. The new design should not use the same wall plane, roof line, or cornice line of the existing structure.


# Chapter 4 – Rehabilitation

# Link: Chapter 4 Rehabilitation

D. Entrances, Porches, and Doors

- 1) The original details and shape of porches should be retained including the outline, roof height, and roof pitch.
- 2) Inspect masonry, wood, and metal or porches and entrances for signs of rust, peeling paint, wood deterioration, open joints around frames, deteriorating putty, inadequate caulking, and improper drainage, and correct any of these conditions.
- 3) Repair damaged elements, matching the detail of the existing original fabric.
- 4) Replace an entire porch only if it is too deteriorated to repair or is completely missing, and design to match the original as closely as possible.
- 5) Do not strip entrances and porches of historic material and details.
- 6) Give more importance to front or side porches than to utilitarian back porches.
- 7) Do not remove or radically change entrances and porches important in defining the building's overall historic character.
- 8) Avoid adding decorative elements incompatible with the existing structure.
- 9) In general, avoid adding a new entrance to the primary facade, or facades visible from the street.
- 10) Do not enclose porches on primary elevations and avoid enclosing porches on secondary elevations in a manner that radically changes the historic appearance.
- 11) Provide needed barrier-free access in ways that least alter the features of the building.
  - a. For residential buildings, try to use ramps that are removable or portable rather than permanent.
  - b. On nonresidential buildings, comply with the Americans with Disabilities Act while minimizing the visual impact of ramps that affect the appearance of a building.
- 12) The original size and shape of door openings should be maintained.
- 13) Original door openings should not be filled in.
- 14) When possible, reuse hardware and locks that are original or important to the historical evolution of the building.
- 15) Avoid substituting the original doors with stock size doors that do not fit the opening properly or are not compatible with the style of the building.
- 16) Retain transom windows and sidelights.

- 17) When installing storm or screen doors, ensure that they relate to the character of the existing door.
  - a. They should be a simple design where lock rails and stiles are similar in placement and size.
  - b. Avoid using aluminum colored storm doors.
  - c. If the existing storm door is aluminum, consider painting it to match the existing door.
  - d. Use a zinc chromate primer before painting to ensure adhesion.






Vicinity Map Not to Scale




PROJECT INF	ORMATION		
	260038000 R-1SH Charlottesville Ci 1825 d: Ridge Street Type: V		
Existing SF: 1625 Proposed Addition SF: Proposed Renovated SF:			
Front Setbac Rear Setbac Side Setback	k: 25'		

# SHEET INDEX

- A0.0 Cover Page A1.1 Site Plan
- A1.2 Existing First Floor Plan A1.3 Proposed First Floor Plan






# Cover Page A0.0

Johnson Hunt Renovation

 204 Hartman's Mill Road | Charlottesville, VA, 22903

 DATE: November 8, 2022
 ISSUE: Schematic Design I






Site Plan • A Johnson Hunt Renovation

 204 Hartman's Mill Road | Charlottesville, VA, 22903

 DATE: November 8, 2022
 ISSUE: Schematic Design I





1st Floor Plan Scale: 1/8" = 1'-0"



Cha

204 Hartman's Mill RoadCharlottesville, VA, 22903DATE: November 8, 2022ISSUE: Schematic Design I

Johnson Hunt Renovation

Existing First Floor Plan A1.2


Ν

True North

Ν

Project North







FLOOR PLAN LEGEND:

New Addition

Ν

True

North

Ν

Project

North



Char

 204 Hartman's Mill Road | Charlottesville, VA, 22903

 DATE: November 8, 2022
 ISSUE: Schematic Design I

Johnson Hunt Renovation

Proposed First Floor Plan

с.

A



Porch Close-ups

Connection to Addition

# 204 HARTMAN'S MILL RD

North Elevation Views











204 HARTMAN'S MILL RD

East Elevation Views





# 204 HARTMAN'S MILL RD

South Elevation Views







# SURVEY 439

BASE DATA

126

# IDENTIFICATION

Street Address: 10	6 Hartmans Mill Road
Map and Parcel:	26-38
Census Track & Block:	4-330
Present Owner:	Robert B. Gray & Rebecca T. Keese
Address:	106 Hartman's Mill Road
Present Use:	Residence
Original Owner:	George T. Nimmo
Original Use:	Residence

# Historic Name: Nimmo House Date/Period: c. 1873 Style: Vernacular Height to Cornice: Height in Stories: 1 Present Zoning: R-2 Land Area (sq.ft.): 2.4 acres Assessed Value (land + imp.): 8,000 + 18,200 = 26,200

# ARCHITECTURAL DESCRIPTION

This one-store weatherboarded house has the rambling form of a house that has grown in several stages and resembles houses a century older. The original section was two rooms with a central hall, its gable roof continuing as a shed roof over a veranda. There was a separate kitchen a few feet behind the main house, and another room and a shed-roofed end porch were soon added to it; and the two sections were connected, creating a weatherboarded hallway between, as in a dog-trot cabin. The kitchen section is two steps above the level of the rest of the house, and its ceilings are a little lower and its gable roof lower pitched. Some years later a much taller one-room addition was built onto the front of the house, with a section of the L-shaped veranda under its high gable roof. The veranda, with its two-part roof, has square posts and simple balustrade. There are three small interior chimneys and an exterior end chimney of brick laid in stretcher bond with an occasional random header. The living room has a fireplace, and the other rooms were heated by stoves. The ornate oak entrance door is decorated in the manner of late Victorian furniture and has a single pane of glass surrounded by small panes of stained glass. The windows are double sash, six-over-six, except those on the veranda, which are two-over-two. Windows and doors have plain trim. A two-room board and batten cottage in the yard was built about the same time as the house. It was completely remodeled in 1974, however, and the exterior end chimney rebuilt and all interior fabric replaced.

# HISTORICAL DESCRIPTION

George A. Sinclair purchased a 94 acre tract from the easte of Edward J. Timberlake in 1870, but did not receive a deed until 1873. He immediately gave Jesse W. Nimmo a deed for 1.1 acres which he and his brother George T. Nimmo had apparently purchased from him previously. The brothers added another half-acre in 1882, and in 1887 divided the tract, with Jesse taking the northern half, on the road, and George taking the southern half, with a right-of-way to the road. Tax records indicate that a building was erected on the property in 1871. The 1873 deed shows a house on Jesse's portion near the road. Tax records indicate that there was a house of equal value on each brother's portion by 1887. Family tradition is that George Nimmo built his house about 1870. Nestled in a nicely landscaped hollow, it was the home of his descendants for 100 years. They owned 12 acres when they sold it in 1973. It was subdivided, and the present owners purchased the house and  $2\frac{1}{2}$  acres in 1976. They are now renovating it.

Deed References: ACDB 71-413, 68-308, 68-325, 82-93, 100-144; City DB 351-103, 351-108, 378-500.

SIGNIFICANCE

This is a small, rambling vernacular farmhouse typical of many others; but, isolated in a small valley within the city, it and its environment are much better preserved than most.

CONDITIONS

Fair

# SOURCES

City/County Records Robert Gray and Rebecca Keese Mrs. Forest N. Morris Mrs. Herbert M: Hammer

#### RECONNAISSANCE LEVEL SURVEY REPORT

DEPARTMENT OF HISTORIC RESOURCE RECONNAISSANCE SURVEY FORM

DHR Idenfication Number: 104-5044

Other DHR Number:

PROPERTY NAMES Nimmo, George T. House EXPLANATION

са

Historic

County/Independent City: Charlottesville State: Virginia Tax Parcel: 26-38 Magisterial District:

Property Date(s) 1880

USGS Quad Map Name: CHARLOTTESVILLE EAST

UTMs of Boundary: Center UTM:

206 -

106 -

:

Restrict location and UTM data? N

#### ADDRESSES

Thoroughfare Name Number

Explanation

Current Name change

Vicinity: Town/Village/Hamlet:

Name of National Register Historic District:

Hartman's Mill Road

Hartman's Mill Road

Name of DHR Eligible Historic District:

Name of Local Historic District:

Physical Character of General Surroundings: City

Site Description/Notable Landscape Features:

The property is a large (2.4 acres) parcel with minimal street frontage (wide enough for a driveway). The driveway, actually a lane lined with cedars and flowering trees, curves back to the house site, which is on a rise above Moore's Creek. The driveway splits at the house, with a forecourt/turnaround area at the front and a narrow parking area at the side of the house. An immense magnolia grows in a low swale east of the house, accessed by brick steps that lead from the front porch. Modern plantings such as hosta, ivy, and flowering plants fill large naturalistic beds at the front yard that are held above the driveway level by stone retaining walls. The rear yard is terraced, leading down to the creek. A remnant earthen dam (for a small mill, electrical generator, or ornamental pond?) remains at the eastern end

96

of the lot in the creek bed. The property encompasses a small area across the creek as well, where various ornamental landscape plantings have been placed.

Ownership: Private

NR Resource Type: Building

WUZITS

Seq. #	# of	Wuzit Types	Historic?
1.0 1.1 1.2 1.3	2 1 1 1	Single Dwelling Stable Poultry Shelter Dam	Historic Historic Historic Historic
TOTAL	: 5		

Historic: 5 Non-Historic: 0

#### PRIMARY RESOURCE EXTERIOR COMPONENT DESCRIPTION

Component	#	Comp Type/Form	Material	Material Treatment
Chimney Door(s) Foundation Porch Roof Structural System Window(s)	1 0 0 0 0	Flue Single Leaf Solid 1-story, 1-bay Gable Frame Sash, double-hung	Brick Stucco Wood Asphalt Wood Wood	Parged Not visible Parged Enclosed Shingle Weatherboard 6/6

#### INDIVIDUAL RESOURCE INFORMATION


SEQUENCE NUMBER: 1.0 WUZIT: Single Dwelling Primary Resource? Yes Estimated Date of Construction: 1880 ca Source of Date: Local Records Architectural Style: Description:

This one-story weatherboarded frame house, with several standing-seam-metal gabled roofs, is an unusual, irregular dwelling of the late-nineteenth century that achieved its present form over the course of many building campaigns. Originally a one-story, side- or center-passage-plan house with an exterior end chimney and engaged front porch, the house has had several historic-period additions. These additions include the formerly detached, shallow-gabled rear/side kitchen wing and its connecting covered passageway, and a tall one-story frame gabled wing with an integral porch. The two-part, L-shaped porch is supported with square posts and accessed by wide steps. Three brick flues complement the one brick chimney. The original windows in the house are six-over-six double-hung wood sash. Windows opening onto the front porch were replaced about 1900 with two-over-two sash. Also at that time, the front door was replaced with the current Queen Anne-style oak and stained glass door. Plain wood trim is present at exterior door and window openings.

Condition: Good

Threats to Resource: None Known Additions/Alterations Description: Post-historic additions include a modern shed-roofed wing behind the kitchen, and a modern wood deck at the rear of the house complex. In addition, the front porch balusters have been removed and front steps reconfigured. Number of Stories: 1.0 Interior Plan Type: Irregular Accessed? No If not, why not? Not accessible Interior Description: SEQUENCE NUMBER: 1.1 WUZIT: Single Dwelling Primary Resource? No Estimated Date of Construction: 1880 са Source of Date: Local Records Architectural Style: Description: This two-room, detached cottage is of board-and-batten and weatherboarded frame construction, with a standing-seam-metal gable roof and rear shed rooms. According to local survey records, in 1974 the interior was gutted and remodeled and the chimney was rebuilt. Condition: Remodeled Threats to Resource: Major Alteration Additions/Alterations Description: Number of Stories: 1.0 Interior Plan Type: Two-Room, Single Pile Accessed? No If not, why not? Not accessible Interior Description: SEQUENCE NUMBER: 1.2 WUZIT: Stable Primary Resource? No Estimated Date of Construction: 1880 ca Source of Date: Site Visit Architectural Style: Description: The stable is a very deteriorated, partially collapsed outbuilding of two levels, clad in board-and-batten siding with open and enclosed units stepping down the sloping site. A rear section, which has projecting vent pipes, may have been used as a meathouse. Construction materials include circular sawn lumber and wire nails. Condition: Ruinous Threats to Resource: Deterioration Additions/Alterations Description: Number of Stories: 2.0

Interior Plan Type: Accessed? No If not, why not? Not accessible Interior Description: SEQUENCE NUMBER: 1.3 WUZIT: Poultry Shelter Primary Resource? No Estimated Date of Construction: 1900 ca Source of Date: Site Visit Architectural Style: Description: One-story, board-and-batten frame chicken house with gable roof. Condition: Good-Excellent Threats to Resource: None Known Additions/Alterations Description: Number of Stories: 1.0 Interior Plan Type: Accessed? No If not, why not? Not accessible Interior Description: SEQUENCE NUMBER: 1.4 WUZIT: Dam Primary Resource? No Estimated Date of Construction: 1900 са Source of Date: Site Visit Architectural Style: Description: The dam is of earthen construction and guite small; it was breached or damaged at some point but remains mostly in place. The dam no longer retains water in a pond behind the house. Condition: Deteriorated Threats to Resource: Neglect Additions/Alterations Description: Number of Stories: 0.0 Interior Plan Type: Accessed? Interior Description: Relationship of Secondary Resources to Property: The cottage dwelling is located immediately behind and adjacent to the main house; the stable is located behind and south of the main house, at the end of the driveway; the chicken house is located behind and slightly west of the main house. The dam is located in the creek bed of Moore's Creek, near the rear property line.



DHR Historic Context: Domestic

Significance Statement:

Brothers George T. and Jesse W. Nimmo began acquiring property along Hartman's Mill Road in 1873. In that year, George A. Sinclair conveyed the deed to 1.1 acres of his 9.25-acre tract to the brothers. The deed shows a house already built on the 1.1 acre-tract, near the road. The brothers bought another half-acre in 1882, and in 1887 divided the enlarged parcel between them--Jesse took the northern half (along the road), and George took the southern half, reserving a right-of-way to the road. By 1887, dwellings of equal value were being taxed on both parcels. Begun after 1873, the George T. Nimmo House is one of the older dwellings in the neighborhood east of Ridge Street. Owned and occupied by members of the Nimmo family for nearly 100 years, the house is an unusual accretive structure with components from at least three historic construction stages. The Nimmo property, a remnant of the twelve-acre parcel ultimately acquired by the family, also retains several early (apparently nineteenth century) outbuildings and an earthen dam, important features of the domestic and agricultural landscape developed over the years. Unlike most properties in the neighborhood, this one is not historically associated with African-American settlement.

#### GRAPHIC DOCUMENTATION

Medium	Medium ID #	Frames	Date
B&W 35mm Photos Slides	15674	1 - 6	4/15/1997 4/15/1997
B&W 35mm Photos	15673	24 - 31	4/ 4/1997

#### BIBLIOGRAPHIC DATA

Sequence #: 1.0 Bibliographic Record Type: Local Records Author: City of Charlottesville Assessors Office Citation Abbreviation: Property Description (by parcel no.) Notes: Legal description: 2.4 acres Sequence #: 1.1Bibliographic Record Type: Local Records Author: Albemarle County Citation Abbreviation: Deed Book(s) Notes: Deed book references:68-308, 68-325, 71-413, 82-93, 100-144 Sequence #: 1.2 Bibliographic Record Type: Local Records Author: Charlottesville, City of Citation Abbreviation: Deed Book(s) Notes: Deed book references: 351-103, 351-108, 378-500 Sequence #: 2.0 Bibliographic Record Type: Survey, Other Author: Citation Abbreviation: City of Charlottesville Architectural and Historic Survey Notes:

"Nimmo House," file no. 196 (n.d., after 1976) CULTURAL RESOURCE MANAGEMENT EVENTS Date: 2/ 6/1997 Cultural Resource Management Event: Reconnaissance Survey Organization or Person: JDP Pres.Consultant: Pezzoni ID # Associated with Event: CRM Event Notes or Comments: MAILING ADDRESS Honorif: First : Last : Suffix : Title : Company: Address: City : State: Country: Zip : Phone/extension: Individual Category Codes: Mailing Address Notes:

Surveyor's Notes:


4.4,97

Nonno Hs. pipes project from vear section -2 level 5+6 stable w/ for amove venting? open + enclid units stepping Lown Will. O Juan lours. very determated, collapsed Lam (Por small mill, elec. gen'r, or ver weaths (111) or nonented pond.) section? only c.s. tumb. + wive hails observed Is both qubie chickon hy? btb+ wbd mod Leck Prame 1.5 61 dg - Wit? mod shed ref. wrong the mod br. drim. 5.5. gable. yoar shed 11II U1 bv. gra 1 6 5  $\uparrow$ are ar-med Swale HMR

Map & Parcel: 33-70 Built: 1958 Surveyed:

Address: 301 East High Street Name: City Mortgage and Insurance Building

File No. 57



Mimmo House (106 Hartmans mill Rd formd: brick piers, stone flet = forma band chimner, occasional header rear on grand shutters 6/6 partition come thom rear wall porch windows 2/2 transomover feft clower stained glass panes around edge st sa posta v reiling porches under main roaf; simple brick walks everywhere ONAL PORCESSOR trees cornice bough as if had is refter itelant west floored belong Righer, 2 -t-trad higher sedling gower canged ridge same ht me cottage board + talks

City Tax Records Nimmo house Robt B + Rebecca T. Keese Gray 9/17/76 378-500 \$32,000 Wm & + Marg F. Heney 9/21/73 351-108 23,500 entrura redución " 103 Charles & Young, Jetal " Intestate George F. Nimmo est '64 42,500 11, 81 acres la a 11 skswar 35 dad of porten 11 12/18/93 II T 6-100-144 " 82-93 es 1 68-308 " 68-309 plat ave constr 57 rooms, 12 baths 010-'66 built to stone found, wood of a siding metal gable roof hand after plaster doitbasement 2 fireplaces + (new 1/8/14 - 1 story frame oftage, 2000 bith 4/22/66 - bath in cottage & house & addition 10/64 heat

2 stype above boat old parting Juck old B not oldest sast br ling in hall weatherboard 5 horiz panel, cross Boll doors for barn cottings boad & batter, stop kings she say rear older ; he says center

der T- 1883-8/14/64 Came 1885-1969 (5/13)

(ty DB 351-105 Vimme fam -> Charles A Young et al \$42, 9/19/13 parcele 38, 39, 40, 45, 467 on City Tax map #26 (attached) cemetery escluded \$47,500 house 2. 49ava -> Haney 351-108 Lend Sum 9/19/73 194,25 N Payne A 460,65 1.16 ac 92.74 580 #37 N Æ 40 1, 13 ac 0,86 ac # 38 1,19ac 7.06 Johnson # 37 Valentine # 45 Banks 3,35 ac Douglas Rougement =67 5, 25 ac Moords Cerk Hartman Milling Co (ACDB 100-275)

5-9-14 57-463 2:10-2:55 3,05-4:00 Nimo alf DB 68-308 Attack Circuit locort decree 5/14/1869 in Joro Woo AM Timberlake 7/17/1803 of authority to sell. I's are lot "on son side of red leading fi Ch'ille by way of Ridge St to Henry Hartman's mill' James Lobban, comme sold to be Sinclair 1870 Sinclair > Jessie W Nummo - I acre of truct + amall piece Geo A & Olenna F Sinclair & Dravy Wood, comm. -> \$190 Jessie W. Nimmo 1.1 acres of all improvemente (road) 4.40 8°2 P 佃 la yr 33 4 10 5 N rin 0 4p 36l

577-168 46554 55-13/17) 4000 54-47 30-776 4,75 47-487 106 F Wills ->H Hartman 1849 9.25 1.6 1.58 14 " 25-526 17 Wm + Harriel Jeffices -> Wm A, Bilb + E) Timberlake #100 perace A 57-482 14 acres 3 rods + 14 perches (15a) near ch'ille At wad corner to\_Cook + allex barrett, of barrett line to branch to spring, new line along branch, to Dr. Destehis line 1859 subdivision of 5 acres on south side of road to Hartmans mill A 88-23 3/1883 bet Chapman on west & J. I Timmo on east, "allotted by comme & Patterson, RKI-langan, & E wolfe to Wm A 3 cbbs estate \$1869" A 57-168 3/4/1859 15 acres (14, 3roods, 414 perches) in suit of Thos + Drury Wood, trusters of Geo W Turpingles, aget Fontaine M, Wells & Wells to pay \$725, 8757 Fontaine Mwells set bought fre Thos & drung wood 1/15/1853 Verye Care paid + took over land Welle sold to wm Jeffier \$ 59 per ave = \$ 859,41 A 53-357 andrew & Faish sold beinge M Turpen son 15 acres (14, 3,14) & Imi 5 E of th'ville & ady James A Leitch, Rook, alex, barnett, & others Twyin has since conveyed his int to Dravy Wood as Truster 12/11/1853 6/12/1854 12/11/1852 indentive made 6/12/54 bet andrew J& mother & Farish inf apportenances, no mention of Blog no del to antria Jean multice informed from re-check dacke from this point; are 53-357 & 46-384 same? 

Oak Hill estate - but down to Bar 67-730 1873 4/10/1882 micijak u oode & JR Taylor -> Geore + Jesse W Nemo under 10/9/1846 deed of baust for GA Sexchair lat 50 03 100 -144 And the second lot. 82-93 4/4/1887 7/17/1873 Deo A & Blenna F Sinclair. + Anwry Wood apper commer -> Jease W. Numme et that 68-305 & Sunda ber & Jesse ger want duride both tracte. ber T. Nimme - southern portion of both tracte of right of way three Jesse's section Jesse W. Nimmo - northern portion of both tracks of access to spring on bed's portion ; all read frontage, 287' back on west & 309' backon east, 123' arrow back (seeaboure) 82-93 \$ 107.72 pet part of 7,1 acre powel conveyed to 6 A Sunclair by 4/10/1883 Driving wood commer in chancery cause Timberlake in Timberlake 8/8/1874, '2 acre, '2 lot ; other half to The on road, adj their other lot

2:40-All Chancery John W. Timberlake os a m Timberlake at al duride treact of land bit this estate +W m A. Bibles 7-175 #1 - 5 acres - Wm A. Bibb estate 5/19/1869 #2-9, 2 acres - Edw. J. Timberlake estate James Lobban authorized to sell #2 ACDO 6832 CA Sinclair - Jesse W Minmo 1, 1 an thirdete 7/17/1873 2 -> Geo W. Minmo "+ all improvements thereon" 71-413 James Lobban, comme of 7/17/1873 Contragues confirms sale to Sinclaire to clear Minmo table

1180 1 : beult 1870 - 600-580 Nimmo ber Sinclairest 4924 ac th'o + 4000 = 24, 612 1871 the Tos EJ Timb, " 143/4 ac strond + 0 = 1180 n 11 11 n 11 11 11 143/4 11 3/4 Zal list + 0 = 590 1840 11 1/2 11 1865 11 11 11 11 1860 bibes w Twyson Toka 1873 Ch'To #3 11 11 11 11 11 1250 +600=1180 beo Sinclair st - same large tract east 1873 same Jessen vier Nummo - Tioac ymi sch + 150-220 1874 From E Timbedake ---- fr & A Sinclaire 1020 Timbedake est 123gar + 450 -- ++2+ EJ Timbedake est 123gar same (both 1875 Numa + 200 = 350 1876 1st Dist 11 1874 +200 = 330 1879 and 11 1884 + 270 = 400 1886 1889 same 1 1891 (also's phonol Jessie wy Geor Rect James 20, " Jessie wy Geor + 270 = 605 l. lac + -- = 40 1/2 11 4/5-ac + 150 = 325 Jessen 1896,1901 +150=325 4/5-ac beo T

1917 #1 anned GT Nimma 4/5 ac 100 + 160 = 260 1921, 23'25 200 + 400 ~ 600 to 1915 reas 100+160=260 4 Finder bought 1870 Sincleir bought house that yr & most have built house that yr " building acturity 1873-74, 1880-85, 1915=20 summary 14<sup>3</sup>/4ac + 0 1860-1870 E) Timboulake est = 590 E & Timberlake est 14 3/4ac (1180) + 0 = 1180 1871 14<sup>3</sup>/4ac (5-80) + 600 1872-73 EJ Timberlake est = 1180 123/4 ac ) (570) + 450 = 1020 1874-75 EJ Timberlake est 1.1ac (70) + 150 " Jesse W & beat Nimma = 220 \$10 1876 Jesse W& Bes T Nimmo (150) + 200 - 350 1847-84 Jesse W& Geo T Nummo (130) + 200 = 330  $15-5-1 \quad 5-5 \quad 5-1-1-1 \quad 11-1-11$ 

Jesse W. Mi bought beau 1273 Nim 6 eorge T, Mimmo c 1855 1- 1935? Jesse W. Mimma - 1911 James Minnos -c.1917 George F. Minno - annie E. T. homason 1883 - 19643 - 1885 - 1969 - Robert H. Nimmo, 1918 - 1977 - Charles " 7, -01965 1615 Keith Valley Rd 3-8460 Waskington Waskington -LaurisT. " × \* - Murray F. " - Mrs. Herbert M. Hammer (anna Minne) 1615 1629 Valley Rd Ch 3-8460 \* Ch'aille ER - Mrs. Forest M. Morris 973-6532 Northfielde Mor 973-5891 Earlypide Ch'olle - Mrs. Thos. P. Melson 12 chn \* lived in Mimmo house 1960's

Robt Gray 6-7576 wife is Rebecca Keyes Nimmos & new owners have they done a deed search ? how far back have they traced house? may 2 × oux their research? what does tradition say about who built it, when, what place it was on ? what have they been told? how many generations of Nimmos? (copy cem?) additions, what part is added name herge in hergef Geo Thos Nimmo built it > 100 yr "ung over 100 yr ago" 204 yr ago thery "mybe a little be & 1865 - her gf "Nimmo", not "Neemo" enpenter - contractor Mrs Hammer 3-8460 back hall elways " bath was porch, put in fireplace 2" allage of fireplace , age house hergm's help Sremodeled now spring, graveyard, old trees Tonsler's place at end of St old St Clair tract ? Nimmos there 200-300 yr ? uncle fim Mimmo, lived the Leanna Simmo 108 Hotmissing) " Jesse '' house gone (at eat, to brive) aunt's "' " Mary Nimmo Brown -> What was Jesse Nimmo house like? h & dr & fireplace room first - k was sep bldg front room some years later, gf said be Jessie home was 2-story cottage (& = playhouse for fa's sie, then 7 bogs slipt there nouse there too Mrs Morris more there too bought 1868 gf b 1852, older than wife

# Complete Picture Not Given on Housing Location, Ridge Lane Opponents Charge

A newly formed Committee Against the Ridge Lane Site today charged the Redevelopment and Housing Authority with 'disregard' for the residents of the site and failure to "give a complete picture" of the property.

The committee, which was formed this week to fight the proposed location of a public housing project at Ridge Lane, has a nucleus of about a dozen members but claims support from numerous other Charlottesville residents.

Chairman of the group is Thomas P. Nelson of 1603 Del Mar Dr.


The committee's purpose, Nelson said, is to give the voters "a clearer picture of the proposed site for the low-rent public housing project on Hartman's Mill Road.'

Ridge Lane is located off Ridge Street south of Hartman's Mill Road. As proposed by the Authority, it would consist of 20 acres, much of it vacant land lying behind houses on the two streets.

The Authority has said eight families and four individuals would be displaced by the project.

In the center of the site is the Nimmo home occupied by Mrs. George Nimmo, her daughter and son-in-law, Mr. and Mrs. Herbert Hammer, and two sons. Murray and Lewis Nimmo. The home is said to be over 100 years old.

In a statement issued today, the committee said A. E. Arrington, executive director of the Authority, "has failed to give a complete picture of this site. He has shown, publicly, utter disregard for the residents of this area.



Nimmo Home Stands in Center of Proposed Housing Site

"including the Nimmos who have owned property here for owners has worked hard for over 150 years. South of Hartman's Mill Road are about a dozen homes, including the Nimmo home, that will be lost if this proposal is approved (in the referendum Tuesday)."

The committee added that homes of middle class, high income Negro families border the site on Ridge Street and Hartman's Mill Road.

"These 50 or more land owners will have their lots chopped "Several white families live in off 165 feet from the street, family cemetery, a number of to the trades of their

"Every one of these property what they now have. They could not possibly duplicate their holdings if they should have to sell.

"The committee cannot overemphasize the fact that the Ridge Lane site is not a slum area needing redevelopment. This area in 1961 was designated as a good location for future middle class and high income Negro homes."


The committee added that a . I dia man


Urging a vote against the site, the committee called on each voter "to examine his conscience before recommending that these graves be touched" or that "these homes and land which are the fruits of geerations of hard work be stroyed."

Nelson said he would . mend that the housing in stages in the Car area as an alt


Lane.

Negative Nos. 15673, 15673 Leslie A. Giles, Dan Pezzowi File No. 104-5044 Name George T. Nimmo House 4 25 out building views Photographer Leslie A. Giles, ] Contents & Extentions of house landscape view Town-City Charlottesville 4/1997 Date 196












Negative nos. 15673, 15674 196 Date 4/1997 File No. 104-5044 Name George T. Nimmo House <del>Town</del>-\_\_\_\_ County Charlottesville Photographer Leslie A. Giles, Dan Pezzoni Contents & Exteriors of house 425 out building views 1 landscape view











#### CITY OF CHARLOTTESVILLE


Department of Community Development City Hall Charlottesville, Virginia 22902

Nimmo House

# 196

106 Hartman's Mill Road

NO PRINT



DI: Other Business

Mall Trees:





TO:	Riaan Anthony, Deputy Director -Charlottesville Parks and Recreation
FROM:	Steve Gaines, Urban Forester - Charlottesville Parks and Recreation
DATE:	June 27, 2022
SUBJECT:	Hazard Trees - Charlottesville Downtown Mall

The Department of Parks and Recreation is responsible for the maintenance of Charlottesville's Downtown Mall. The health issues with canopy trees along the pedestrian corridor continue to be a concern. As the trees along the corridor are approximately 45 years old (trees were planted in 1976) symptoms and signs of significant decline are apparent. This memo outlines reasoning for mitigating potential hazards and failures of canopy trees in the near-term, as well as plans for moving forward with proposals (RFPs) for long-term mitigation strategies.

The Downtown Mall complex includes 73 trees in total. Species composition includes Willow Oak, Shumard Oak, Gingko, Red Maple, and Norway Maple; with Willow Oak being the most common tree in the mall median. There are seven trees (five Willow Oaks, one Ailanthus, and three Red Maples) that should be removed within the next three months. These trees show signs of significant decay and could structurally fail, giving rise to pedestrian hazard. Visual symptoms of decline seen in these trees include obvious loss of vigorous growth, yellowing leaves, and dead branches. Detailed signs of causal agents contributing to decline of these trees include visual appearance of fruiting bodies (mushrooms/basidiocarps), and obvious evidence of insect activity (see attached figures). Additionally, in accordance with Charlottesville's Invasive Vegetation Management Plan, a mature Tree of Heaven (Ailanthus) is recommended for removal.

The Downtown Mall canopy trees are an enormous asset to the city of Charlottesville. Due to the high level of stress that the trees are growing in, species composition and relative age of the canopy trees are a concern. These urban trees undergo environmental stresses such as severe restrictions for root development, increasingly high temperatures (heat from overhead sunlight as well as heat reflection from hard surface pavement), air pollution, drought/excess water extremes, insects, and fungal/bacterial pathogens. In general, stressed trees are more vulnerable to attacks from pathogens and/or insect infections. The fact that most of the trees are of one common species (Willow Oak) and are roughly the same age (approximately 45 - 50 years old), conditions are favorable for some sort of infection/infestation. The best method to combat potential infection is to encourage diversity of species composition and structure (size and age class), and to manage any known health defects before infection/infestation can spread.

Removal of severely compromised trees are suggested by the Charlottesville Urban Forester. Similar suggestions have been echoed by specialists that recently observed the trees in question. Recent specialists include tree health experts from Big O Tree and Lawn Service, Bartlett Tree Experts, Virginia Cooperative Extension, and private consultation from Tree Matrix LLC. Any mitigation activity should be well communicated and should include several information sessions for the public. As any tree work in the mall will be closely observed, taking the opportunity to educate the public on tree health and pedestrian safety is paramount. Parks and Recreation staff will be available for workshops or public information sessions as deemed necessary.

The process of tree removal will be planned and executed in a manner that causes the least disruption possible to pedestrian and business activity. Any trees scheduled for removal will be removed as quickly as possible to minimize disturbance to pedestrian traffic and businesses.



6



Subject here November 9, 2022 Page: 2

It is important to note that a failure to act can and will lead to eventual tree failure, and potential hazard to pedestrian safety, as well as destruction of public and/or private property.

The issue of transitioning the tree canopy to a more sustainable species composition and age class has been a consideration for several years. Charlottesville has been fortunate in that the trees occupying the downtown mall have been as healthy as they have been for the last 45 years. As stated earlier, stressed trees invite a myriad of biotic agents (pathogens/insects) that could have severe effects on tree health. As the trees are roughly the same age and same species, an organism could easily spread throughout the population and devastate the urban canopy.

In December of 2015, the city of Charlottesville hired consultants to report on the conditions of each street tree occupying the mall. All findings and recommendations were presented in a final report to the city and has been available on the city's Urban Forestry website through Parks and Recreation. The 2015 report details health status of each of the mall's 73 trees and warns of potential health concerns often encountered with monocultures. Of particular concern for the authors were the level of vulnerability of urban trees after prolonged periods of stress. The authors (James Urban, FASLA and Keith Pritchard, ISA) stressed a need to address the lack of species diversity along the pedestrian corridor. Methods for addressing the issue, as suggested by the authors, may include the following:

- Removing individual trees as they decline and become hazardous (with replacement plantings as vacancies become available)

- Removing single blocks of trees at a time (and replacing all the trees within that block)

-Removing select islands of trees at a time (and replanting all the trees within the island)

-Combinations of suggestions as scenarios present themselves

In June of 2021, The Department of Parks and Recreation developed a draft Request for Proposals (RFP) for Charlottesville's Downtown Pedestrian Mall. The RFP will be finalized as soon as possible. The RFP will solicit consultants to formulate guidelines for the long-term management of the mall as a constructed and planted landscape of historical and cultural significance, with considerable attention to trees as an essential element of the design.

Parks and Recreation anticipate a high level of public criticism throughout this process. Potential mitigation strategies may include a high degree of public involvement, public education/engagement throughout, and a creative use of generated wood products.







<u>Tree 1</u>




Figure 1: Large Diameter Willow Oak 24-26 inches in diameter. Significant wound starting approximately 5 feet up on tree bole. Obvious internal decay with carpenter ant activity.

Location: Dining area – Petit Pois



Figure 1: Large Diameter Willow Oak 24-26 inches in diameter. Significant wound starting approximately 5 feet up on tree bole. Obvious internal decay with carpenter ant activity.

Location: Dining area – Petit Pois

#### <u>Tree 2</u>



Figure 2: Red Maple, approximately 12 inches in diameter. Two significant wounds on tree bole (Approximately 4 feet high and 7 feet high respectively). Obvious internal decay at crotch, with additional infection evident in wilting leaves (probably Verticillium Wilt – unconfirmed currently). Location: Adjacent to Dining area – Petit Pois



Figure 2: Red Maple, approximately 12 inches in diameter. Two significant wounds on tree bole (Approximately 4 feet high and 7 feet high respectively). Obvious internal decay at crotch, with additional infection evident in wilting leaves (probably Verticillium Wilt – unconfirmed currently). Location: Adjacent to Dining area – Petit Pois

<u>Tree 3</u>




Figure 3: Willow Oak, approximately 22 inches in diameter. Obvious wound 5 feet high on tree bole, carpenter ant activity present. This wound is also flared and misshapen across the backside of the bole, further indicating instability. Location: Adjacent to 106 East Main Street




Figure 3: Willow Oak, approximately 22 inches in diameter. Obvious wound 5 feet high on tree bole, carpenter ant activity present. This wound is also flared and misshapen across the backside of the bole, further indicating instability. Location: Adjacent to 106 East Main Street

#### <u>Tree 4</u>



Figure 4: Willow Oak tree, approximately 12-14 inches in diameter. Tree displaying a few dead limbs in the upper canopy as well as large fruiting body on the stump (common indicator of severe internal decay). This tree has been heavily pruned over the years and is showing loss of vigor. Location: Across from Rockfish Brewing Company.



Figure 4: Willow Oak tree, approximately 12-14 inches in diameter. Tree displaying a few dead limbs in the upper canopy as well as large fruiting body on the stump (common indicator of severe internal decay). This tree has been heavily pruned over the years and is showing loss of vigor. Location: Across from Rockfish Brewing Company.

### <u>Tree 5</u>




Figure 5: Ailanthus tree, approximately 10-12 inches in diameter. This tree is considered extremely invasive and is listed in Charlottesville's Invasive Plant Management guidelines. Location: growing behind the Whiskey Jar restaurant.




Figure 5: Ailanthus tree, approximately 10-12 inches in diameter. This tree is considered extremely invasive and is listed in Charlottesville's Invasive Plant Management guidelines. Location: growing behind the Whiskey Jar restaurant.

#### <u>Tree 6</u>



Figure 6: Willow Oak tree, approximately 14-16 inches in diameter. Tree has several dead limbs in the upper canopy and has been intensively pruned in the past. Tree displays fungal fruiting bodies toward the top branches, as well as bacterial weeping, both indicating internal decay. Location: Across from Wells Fargo Bank.



Figure 6: Willow Oak tree, approximately 14-16 inches in diameter. Tree has several dead limbs in the upper canopy and has been intensively pruned in the past. Tree displays fungal fruiting bodies toward the top branches, as well as bacterial weeping, both indicating internal decay. Location: Across from Wells Fargo Bank.

<u>Tree 7</u>




Figure 7: Willow Oak tree, approximately 16-18" in diameter. Standing tree has declining/dead branches toward the top of the tree in addition to swollen areas on tree bole (indication of internal decay). Location: Across from Parks and Recreation building entrance.

## Tree 7






Figure 7: Willow Oak tree, approximately 16-18" in diameter. Standing tree has declining/dead branches toward the top of the tree in addition to swollen areas on tree bole (indication of internal decay). Location: Across from Parks and Recreation building entrance.

### <u>Trees 8 – 9</u>



Trees 8-9 – Both trees are red maples and are completely dead. Suggest removing dead trees and replacing with live trees that will provide quality shade for pedestrians. Trees are located directly across from the fountain.

### <u>Tree 10</u>



Tree 10: Red maple tree infected with Verticillium Wilt (probably the same pathogen that killed trees 8-9). Tree will not recover, suggest removing tree and replacing with appropriate species that will thrive and provide shade for pedestrians. Tree location: Adjacent to fountain on downtown mall.

### <u>Tree 11</u>



Tree 11: Red maple tree displaying two significant wound sites as well as significant decay. The structural integrity of the tree is compromised and should be removed. Suggest replacing tree with a more appropriate species that will contribute to shade services and pedestrian safety.

Tree location: Adjacent to fountain on downtown mall.



